

News



Volume 29 • No 6 • December 2012

Sidevalve



Features this issue

Panhard Rod Kits for Uprights

Winter-Starting Old Sidevalves

Cotswold Historic Sporting Trial

Don't Rely On The MOT

Journal of the Ford Sidevalve Owners' Club

Membership renewal
form enclosed

www.fsoc.co.uk

Contents

- 3 Editorial
- 4 Events; Federation Report
- 5 Regional News: Cambs, Lincs & Norfolk
- 6 Regional News: Scandinavia
- 7 Regional News: Yorkshire
- 8 Regional News: North London
- 9 Regional Report; A Word from Wilts
- 10 Pre-War Register
- 12 E83W Register
- 13 New Club Spares
- 17 Order form
- 18 Pop Shopper
- 21 Panhard Rod Kits for Uprights
- 22 100E Register
- 23 Anglia, Prefect & Pop Register
- 25 Specials Register
- 27 Letters & Emails
- 30 Winter-Starting Old Sidevalves; Cotswold Historic Sporting Trial
- 31 Don't Rely On The MOT

Editorial

John Porter

A month has passed since the requirement for pre-1960 cars to have an annual MOT test has ceased. As I write this editorial my local garage should have had a copy of the letter from the minister regarding the situation as it affects our Sidevalves (see Letters & Emails). A fair number of classic car people I have spoken to are intending to continue with a voluntary test and we now know that the test centres will be able to oblige. Either way, we are all required to keep our Sidevalves in roadworthy condition but it is nice to have a third party inspect and pass the car. Are those that carry out spot checks on the highway able to form a view of the roadworthiness of some classics? The extra play in our steering boxes could be deemed to be 'too much' or 'unsafe' without some technical knowledge. Lights, tyres and soundness of the exhausts are straightforward enough to issue an on the spot fine.

Something for the next season. Jill Bradbury, below, is the winner of the AGM driving test – seen here displaying her trophy. Jill had never driven a 100E before the event, which put the rest of us to shame. It is seriously worth a thought as an event in your area when the weather is better, and it makes a change from the ever popular road-run. There are many safe and non-damaging activities that you can get up to in a suitable field ...



Try driving your Sidevalve around obstacles, through narrow gates and parking in a 'garage'. These activities are not fast, nor are you likely to break your car, though your pride may take a hit. They are guaranteed to raise a smile and probably a row with your passenger who obviously knows better. I remember that in the dim and distant past, in a universe far away, a Sidevalve Day (Cotswold Wildlife Park?) featured a selection of these activities. Driving blindfolded with only your passenger to guide progress and gauging how close you could drive your Sidevalve to a bamboo stick

certainly broke the ice between members who had never met before. There was even an egg and spoon race, with the passenger holding the spoon and the driver attempting the course without unsettling the egg. So why not give it a try next year?

Winter draws on

No doubt you will be reading this magazine as you prepare for one of the biggest national and international festivals – Christmas. No matter what your feelings are about this time of year, you know that something is waiting in the garage! Unless you extended your central heating system, it is not the best place to be over the Christmas break, with all that dead time that we endure with most of the services shut down or on short hours. The last event may now be two or three months away and you put the car away without a thought. Now is the time to do something about it. The most obvious thing to do is see if the engine will start with the load of stiff 20/50 grade engine oil. Don't chance it – put the battery on charge the night before you pull the starter knob. If you have an unheated garage then a quick wipe over the ignition leads and a spray of WD40 or similar will give you half a chance of successfully getting a result. With the engine running (don't just leave it idling for five minutes and turn it off), back the car out and keep the engine running at a fast idle – choke in! Run the engine for at least 20 minutes to get water and oil up to working temperature. If the car is not SORNed and is insured then take the car out for a 20-minute drive, provided it is not wet and salty. This is better as the gearbox and axle get stirred up, as well as the brakes and clutch.

It is best to store your Sidevalve with the recommended antifreeze mixture as it will keep all the gaskets from drying out, as would happen if you do it the old way and just drain the water out. For the sake of the tyres, jack the wheels just off the garage floor on stands. If you are going to leave the car for the rest of the winter, remove the plugs and put some Redex or similar down the bores – put the plugs back in to keep out moisture. Also, do not store an engine for the winter period with old and possibly contaminated oil in the sump. Apply some wax polish to protect the paint from a damp atmosphere. Wipe some Waxoyl over the chrome – best done with the aerosol version to get behind the bumpers especially. Keep the dust off with a light man-made fabric sheet – Halfords do a very suitable sheet at a good price. Check the charge of the battery every few weeks or get one of those battery conditioners that maintain the state of charge without over-charging. These precautions will lessen the pain come spring.

All that remains is to wish all a very Happy Christmas and a fruitful New Year.



Sidevalve News

ISSN 0966-9140

Published by the Ford Sidevalve Owners' Club Limited.

Registered Office:

Slade Legal, The Greenhouse, Stratton Way, Abingdon, Oxon OX14 3QP

Reg. No: 2604000 (London).

Editorial/Advertising address:

Sidevalve News Editor,
PO Box 1172, Abingdon S.O., OX14 5WA

FSOC Web Site:

<http://www.fsoc.co.uk>

Sidevalve News is published every two months on the fifteenth of the month, commencing February.

Copy deadline is the tenth of the month preceding publication.

Ford Sidevalve Owners' Club Limited and its officers cannot accept any liability whatsoever resulting from any technical advice or recommendation given within this publication. Publication of any such article, letter or technical recommendation does not imply in any way recommendation, concurrence, opinion or agreement by the Ford Sidevalve Owners' Club Limited or its Officers.

Advertising:

Classified advertisements appear at the editor's discretion, subject to submission by the tenth of the month preceding publication. This is a free service for both members and non-members, although an individual may not normally have more than two advertisements in any one issue. Inclusion is subject to copy being supplied in BLOCK CAPITALS with a

maximum of 28 words, including area and phone number. Please use the form provided. No advertisements will be accepted by telephone.

The FSOC's status as a mutual trading company precludes the acceptance of paid advertising from third parties who are not fully paid-up FSOC members. Advertisements are accepted and printed in good faith; please take care before parting with any money.

Exports:

The Club's Insurance Policy excludes sales of new or second hand parts to residents in the USA or Canada or people intending to export the parts, or cars to which parts have been fitted, to the USA or Canada.

© FSOC Ltd 2012. E&OE.

All trademarks acknowledged.

Cover photo by Tony Young.

Club Officials

The FSOC is run by a committee of volunteers, who are unpaid and run the Club in their spare time. Please write to the correct official, stating membership number and enclosing a SAE. Please telephone at stated times only.

Chairman: John Porter, 16 Nuneaton Lane, Higham-on-the-Hill, Nuneaton, Warks, CV13 6AD
E-mail: sv1172@aol.com.

General Secretary: Shirley Wood, FSOC Ltd., PO Box 1172, Abingdon, S.O., OX14 5WA. E-mail: generalsecretary@fsoc.co.uk.

Membership Secretary: Jennie Thake, FSOC Ltd., PO Box 8095, Bishop's Stortford, Herts, CM23 4XZ. E-mail: membershipsecretary@fsoc.co.uk.

Treasurer: Tony Young, 23 Pepingstraw Close, Offham, West Malling, Kent ME19 5PB.

Spares 8hp, 10hp Models: Shirley Wood, FSOC Ltd., PO Box 1172, Abingdon, S.O., OX14 5WA. E-mail: generalsecretary@fsoc.co.uk.

Stephen Wood, 14 Piping Green, Colden Common, Winchester, Hants, SO21 1TU.

Spares 100E, 107E: Neil Patten, Badgers Keep, Verwood Road, Wimborne, Dorset, BH21 8LJ. E-mail: neilpatten@btinternet.com. Tel: 07796 964484 and 01202 933525, 6.30-7.30pm only.

Technical Advisor, 8 & 10hp: John Pole, 26 Croft Bank, Malvern, Worcs, WR14 4DU (written requests for advice). Tel: 01684 564 829. E-mail: technical810hp@fsoc.co.uk.

Technical Advisor, 100E, 107E: Jim Norman, 7 Chaucer Place, Abram, Wigan WN2 5QB. E-mail: j.norman2007@btinternet.com. Tel. 01942 861043 (7.00pm-9.00pm only please).

Regalia and Books: Shirley Wood, FSOC Ltd., PO Box 1172, Abingdon S.O., OX14 5WA.

Events Co-ordinator: Brian Cranswick, 18 Bellmans Grove, Broadacres, Whittlesey, Nr Peterborough, Cambs. PE7 1TX. E-mail: events@fsoc.co.uk.

Web site/Pop Shopper: Mark Bradbury. E-mail: webmaster@fsoc.co.uk / pop.shopper@fsoc.co.uk.

Publicity: Godfrey Hands, 9 Douglas Road, Briercliffe, Burnley BB10 2JQ. Email: publicity@fsoc.co.uk.

Sidevalve News Editor: The SV News Editor, PO Box 1172, Abingdon S.O., OX14 5WA. E-mail: editor@fsoc.co.uk.

Regional Co-ordinator: John Duckenfield, 75 Oldfield Road, Stannington, Sheffield S6 6DU. 0114 2341550 (no calls after 9:00pm please). Email: regionalorganiser@fsoc.co.uk.

Registrars (Specific Model Enquiries and DVLA Applications)

Pre-War Yvon Precieux, Cliff Lodge, 9 Cliff Road Terrace, Wemyss Bay, Renfrewshire, PA18 6AP, Scotland. Email: prewregister@yahoo.co.uk.

E83W Yvon Precieux (Acting E83W Registrar). Contact details above.

Anglia, Prefect, Popular Andy Main, 26 Harty Avenue, Wigmore, Gillingham, Kent, ME8 0NA.

Specialist Applications Vacant.

Specials Ian Woodrow, 1 Baddesley Close, North Baddesley, Southampton, Hampshire, SO52 9DR. E-mail: specialsregistrar@fsoc.co.uk.

100E/107E Tony Lloyd, 180 Walton Road, Walton on the Naze, Essex. CO14 8NA. E-mail: 100ERegistrar@fsoc.co.uk.

Regional Contacts and Regional Groups

Regional groups are organised on a voluntary basis. Interests can include social gatherings offering mutual help and advice, outings, events and even holidays. To start a group in your area please contact the Regional Co-ordinator. When telephoning the Regional Co-ordinator or any of the Regional Contacts listed below, please call between 7.00pm and 9.00pm ONLY.

Bristol and South West: Ivor Bryant 01454 411028. *3rd Wednesday: Horton Historic Vehicle Club, Horton Social Club, outskirts of Chipping Sodbury. 8.30pm.*

Cambs, Lincs and Norfolk: Brian Cranswick 07984 631064. E-mail: popular103c@yahoo.co.uk. Please ring for details.

Coventry and Midlands: Geoff Hammond 02476 334201. E-mail: hammond.geoff@talktalk.net. *2nd Tuesday, Queens Head, Meriden, Nr Coventry. 8.00pm.*

Devon and Cornwall: Ian Rooke 01752 266018. *Please ring for details of local activities.*

East Essex and South Suffolk: John Gater 01206 240100. *Please ring for details.*

Glos, Hereford and Worcs: John Pole 01684 564829. Email: johnruthpole@googlemail.com. *3rd Thursday: The Farmer's Arms, Birts Street, Birtsmorton, Worcestershire: 7.30pm.*

Hampshire: Mick Crouch 023 8069 2359. *Please ring for details.*

Kent: Richard Greenaway 01580 892169. E-mail: mtgreenaway@yahoo.co.uk. *Third Wednesday: The Early Bird Pub, Groveswood Drive North, Weavering, Maidstone, ME145TQ (next to Tesco on the Grove Green Estate) 7.30 pm.*

East Lancs: Steve McKenna 07885 433496. Email: steve.mckenna@rocketmail.com. *Third Wednesday of the month, Duke of Buccleugh pub in the centre of Waterfoot (between Bacup and Rawtenstall) 7.30 for 8.00pm.*

London North: Robin Thake 01279 659245. *1st Monday: ring or e-mail before meeting to confirm venue.*

London South East: Stan Bilous 020 8764 7068. *Please ring for details of local activities.*

Merseyside: Joe Wheatley, 40 Newchurch Lane, Culcheth, Warrington, Cheshire WA3 5RR. E-mail: joe@ajwheatley.freemove.co.uk Mobile 07831 622075. *2nd Monday: Bottle and Glass, St Helen's Rd, Rainford. 8.00pm.*

North West Midlands and Welsh Borders: John Crowe, Brook House Farm, Norbury, Nr. Whitchurch, Shropshire SY13 4HY. Tel 01948 663768. Email: john.crowe3@btinternet.com.

North Yorkshire and Teesside: Martin Hatfield, 25 Halstone Drive, Northallerton, North Yorkshire, DL6 1SP. Tel: 01609 771984. *Please contact.*

Northamptonshire: Danny Moody 01604 810095. *1st Thursday of the month, Griffin's Head, Mears-Ashby (between Northampton and Wellingborough), 8.45pm.*

Nottinghamshire: Robert Marshall 32, Florence Street, Hucknall, Notts NG 15 6EB. Tel: 0115 9556802. romarpop@ntlworld.com.

Scotland - East: Robin Barlow 01356 648876. Email: robin-17_bar@tiscali.co.uk.

Scotland - West Central: Please contact John Duckenfield for details.

Somerset: Tim Griffiths, 7 Rackclose Gardens, Chard, Somerset. TA20 1RG. 01460 67735. Email: rtg13@btinternet.com. *2nd Wednesday: The Rising Sun, Knapp.*

Surrey: Mike Jillians, 54 Grafton Road, Worcester Park, Surrey. KT4 7QP. Tel: 0208 335 3442. Email: michael.jillians@btinternet.com. Please contact for details.

Sussex: David Pickett 01444 483350. *3rd Wednesday: Barley Mow, Selmeaton, A27. 7.30pm.*

Wiltshire: Sally Litherland 01722 323035. Email: salitherland@tesco.net.

Yorkshire: Nigel Hilling 01484 843115. E-mail: nhilling@tiscali.co.uk. *Last Tuesday at NEW VENUE: the Reindeer Inn, WF4 4RL, just off the A642 Huddersfield to Wakefield road near the Mining Museum, 8.00pm.*

International Contacts

Australia: Gordon Cowley, 5 Weebo Street, Gilles Plains 5086. Tel: 00 61 8 8261 7631, email: gordon14days@gmail.com.

Belgium: François Jordaens, Reetsesteenweg, 143, 2630 AARTSELAAR. Tel: 03/844.07.68.

Canada: Les Foster, #101- 210 11th Street, New Westminster, British Columbia V3M 4C9, Canada. Tel. 604-999-4936. E-mail: leswfoster@hotmail.com.

Austria, Germany and Switzerland: Markus Hosch, Brunnmattstrasse 9, CH-4053 Basel, Switzerland. Email: M.Hosch@hin.ch.

India: Bipin Pole, 129 A/1 Chiplunkar Road, Erandawane, Pune, 411004, India. Tel: 912025432153 / 919822190242 (mobile). Email: bipin_pole@hotmail.com.

Ireland: Colm O'Neill, 29 Allen Park Drive, Stillorgan, Co. Dublin. Tel: 01 288 7173. E-mail: williamconeill@circom.net.

Malta: Reniel Pisani, 'Our Nest', St. Georges Road, Ghaxaq, MALTA GXQ 1253. Tel: +00356 79208378. E-mail: renielpisani@hotmail.co.uk.

Scandinavia: Haakon B. Oeverland. Saupstadringen 43 A, 7078 SAUPSTAD, Norway. E-mail: hoeverl@broadpark.no.

Sri Lanka: Lankananda Dela, No. 149, Dodampe - 70017, Ratnapura, Sri Lanka. Tel: 0094 45 2226939 (residence), 0094 71 9667237 (mobile). E mail: lankananda.dela@yahoo.com.

Events

Brian Cranswick

Very little to report as another year swiftly comes to an end. Looking back, the weather for the first part of the season was certainly very wet, with far too many events being completely cancelled or rearranged. Fortunately the final part of the season was a lot kinder. On the plus side you would have been very unlucky if you suffered from vaporisation.

I recently found a photo of myself with my 103E taken in 1975, which was the year I purchased my Pop. Thirty seven years on, the condition has improved with age: if only the same could be said about yours truly!

If you are arranging a Club event, please send full details to the Events Co-ordinator so this can put on the Club website and logged for the purpose of the Club's Insurance cover. I have sometimes found that the link from events@fsoc.co.uk does not seem to work and your email can be bounced back to you. Should this happen, please use popular103e@yahoo.co.uk

1st January, Horton Historic Vehicle Club. New Year's Day gathering at Sharpness Docks, south of Gloucester. Contact Ivor Bryant for information if you fancy a run out in your old motor.



31st March & 1st April, Weston Park Classic Car Show, Weston-Under-Lizard, Staffs. Club stand being arranged. Contact Stuart Battersby for details: 07801 306404 or battersby56@sky.com.

21st April, Drive It Day. Full details of activities to be advised.

29th June, Club AGM, Lakeside Lodge, Pidley, nr Huntingdon, Cambs. Further information to be advised.

Federation Report

Mike Brocklehurst

John Porter and I attended the AGM and Conference of the Federation of British Historic Vehicle Clubs Limited on 6th October, held at the Rolls Royce Enthusiasts Club at Paulerspury. Some of the items reported here may well now have come to a conclusion or reached a point where more information will be available and may now have been seen in the enthusiast press.

Presentation of the accounts showed that a loss of nearly £8000 was accrued in the year ended 31st May 2012. By way of explanation we were advised that a number of extra meetings took place during the financial year, in particular concerning the proposed MOT changes and the process of the Ethanol in petrol testing. An exceptional figure of £5000 related to the re-testing involved in the Ethanol lab work where unfortunately the problems of contamination in the initial tests were the fault of the Federation, which resulted in the procedures having to be repeated together with the related costs. The Chairman, Chris Cunningham, reported that the Federation continues to represent some 513 clubs – an increase on the previous year – which represent over 250,000 members in enthusiast clubs throughout the UK. There had been a decrease of 24 traders in the membership which it was thought was a reflection of continuing difficult trading times. Following his report the Chairman stood down after holding the office

for the last three years, his place being taken by David Whale, previously Director of Heritage.

Following the AGM the conference developed the theme of the work of the Federation over the next ten years with particular reference to Legislation, Trade and Skills, and Communication. On Legislation it was confirmed that the Federation's initial thoughts were that all vehicles manufactured before 1920 should be exempted from testing, but as it was felt that a wider view from member clubs was required, enquiries were made. These met with the same statistics produced by DVLA that 1960 should be the cut-off date. One disturbing fact was that 60 e-mails sent to member clubs asking for urgent replies only produced responses from 22 clubs. It was also reported that following pressure from enthusiast groups the DVLA will be offering an alternative MOT-type test, although the details were not as yet available. As a result the Federation had managed to persuade one of the major classic car insurers to hold back on their proposal to introduce their own test in order to preserve the low premiums we all enjoy. One disturbing proposal for the future was a pan-European test for all vehicles with an exemption for all vehicles over 30 years old on a rolling basis. The test would be carried out by machine which would be fed the data of all known vehicles and as a result no deviation from originality would be allowed – so out would go electric wipers on our cars, 12 volt electrics on the Uprights and a whole host of other improvements. This was generally agreed by all parties in the UK as unworkable, including government and DVLA, and we need to keep an eye on developments.

The Federation wished to increase our heritage potential, and to develop the concept of establishing historic vehicles as cultural items and to demonstrate their impact on society.

Continuing support would be given to Trade and Skills and we were introduced to a young man – only 17 – who had recently taken up an apprenticeship with a classic car restorer, as part of an industry which produces a large sum for the the economy – £4.3m according to the Federation AGM – and employs some 27,000 people.

Some interesting facts were given at the meeting, notably that 70% of classic cars were valued under £10,000, which apart perhaps for a few Utilicons and pre-war Tourers covers all our cars. Also, the London to Brighton Run is said to give an increased income of £1.1m to the town and surrounding area. Classic car motoring only contributed to 0.24% of total mileage covered annually by all vehicles in the UK. A plea was put out at the end of the meeting for volunteers to assist in all areas of the Federation's work because, like many of their member clubs, the age profile is getting older and it is proving difficult to attract younger people into our hobby. Surely there is nothing better on a cold winter's day, with snow piling up against the garage door, than to crawl under your Pop or Prefect and take out your frustrations on that stubborn nut, or paint that chassis member that you have been promising yourself you would do all summer when the sun was shining – perhaps not this year, though!

Regional News

Cambs, Lincs & Norfolk

Brian Cranswick

Ramsey Country Show, 30th September

A very enjoyable local show, especially when the weather is kind, and it certainly did not disappoint us this year with a very nice, pleasant day. It was pleasing to see the return of the ploughing demonstrations, along with the usual stalls and museum exhibits. Attendees: myself (103E), Mike Capps (E93A) and Bill Buchan (100E), with a further three sidevalvers from the North London Group – Robin (E04A), David (103E) and Stuart (100E).

End of Season Run, 7th October

Another very enjoyable day with really grand weather, being just perfect for a 'drive it' end of season run. For the local group the starting point was the George Hotel in Whittlesey, using the country back roads through the villages to meet up with the North London group at Godmanchester. The final destination had to be changed at the last minute, to the Hitchingbrooke Country Park, due to a car boot sale being held at the Wood Green Animal Shelter. This was a much better venue than I originally planned, resulting in a really fantastic turnout of members, with six Sidevalves from the Cambs group, including John Roberts bringing both his 300E and a lovely original newly acquired green 100E Anglia. John now owns three Ford Sidevalves. I have to ask the question: has he room for any more motors?

The North London group were also very well supported with a further six Sidevalves, along with Richard Healey driving a rather smart Humber Sceptre. A stray Morris Minor joined in as well, making a great total of 14 cars on the day (5 x Uprights, 7 x 100Es, 2 x non-Sidevalves). Many thanks to everyone who came along: I hope we can repeat this again next year.

And finally

I would like to wish all the members a very Happy Christmas and Happy New Year.

Finally, please note my contact telephone number has changed to 07984 631064.



Regional News

Scandinavia

Håkon B. Øverland

Despite my failed attempt to meet some of the Scandinavian members at the Autojumble at Falun in September, I have for the first time met face to face with one of 'my' members.

My wife Emily (yes, there is more than an old Prefect with that name!) and I made a short trip to Copenhagen at the end of that month. Before we left home I called Søren Palsbo to inform him of our visit. He kindly turned up in the most popular part of Copenhagen (Strøget) where we spent a couple of hours together over wine, beer and coffee. For the occasion my Emily took a picture of the two elderly gentlemen, while Søren took a few snaps of Emily and my good self. Despite a dreadful summer both in Denmark and Norway – as indeed in England as well, I believe – it was a very nice day when we visited Copenhagen. Maybe I am in luck when I am at any FSOC meeting?



Meanwhile, much to my surprise I got an e-mail from far away Sri Lanka, from a FSOC-member there named Dela Bandara. He sent me many pictures of his 107E Prefect, including one where I believe Dela himself appears (top right).

I wish all FSOC members a Merry Christmas and a Happy New Year with lots of time for good sidevalving.

Anything but a Popular

Søren Palsbo: One of the images you get when you search for pictures of Ford Populars on Google is a hand-drawn advertisement for the little Ford, probably dated around 1955.ⁱ Considering that British Ford conceived of the Popular 103E in 1953 with the main aim to produce a reliable but by no means innovative car as cheaply



Mr Dela Bandara from Sri Lanka proudly displays his 'new' 107E Prefect

as possible, one could have expected that the advertisements would emphasise that Popular buyers would get great value for their money. A sturdy construction, but nothing posh!

Nevertheless the Ford people tried to convince the customers that the Popular was one of the most elegant cars ever built and that its boot would give room for a considerable number of big suitcases belonging to the lady of the house! In the Google advertisement in question the lady of the house waves eagerly to her husband as he is parking the Popular in front of their home. The family evidently has the most modern furniture of the mid-1950s (Danish design, who knows?) and Mrs Popular is dressed very smartly indeed. And apparently the design of the Popular 103E beats it all. Quite a challenge!

Don't let me be misunderstood. I pat my Popular 103E regularly to let it know that I love it

but you can hardly claim that it is breathtakingly elegant. Which reminds me of what one of my colleagues said when she saw a picture of my Popular for the first time: 'My father and the father of my best friend were both planning to buy their first car in the middle of the 1950s. We both prayed: "Anything but a Popular!"' My prayers must have been heard as my dad bought an Anglia (100E). My friend's father bought a Popular. A notable social decline!

Luckily, in the many years which have passed since then the few remaining Danish Populars and other Ford Sidevalves have accumulated a lot of interest. And as regards charm, they are unbeatable.

As the history of my car is unknown it could be the 'Anything but' Popular.



ⁱ http://www.stockphotopro.com/photo-thumbs-2/stockphotopro_632951QYV_0340001084.jpg

Yorkshire

Nigel Hilling

General info

Our monthly meetings continue at the Reindeer except for December when we will be back at the Electra Cinema for a Christmas do hosted by Trevor Miller. This should be on Tuesday 18th December but if anyone is in any doubt as to the date or venue then contact me by phone or e-mail.

Compliments of the season to everyone – don't forget to renew your subscription, and I hope to see many of you in the New Year.

Meltham 1940s Weekend

One of a number of nostalgia weekends in Yorkshire is held in the village of Meltham near Huddersfield in July. Trevor Miller and Dinah Bentley are seen entering into the spirit with Dinah's not quite 1940s car (photo 1). The event had a number of attractions including a military parade and a Spitfire flypast.



Photo 1

York Racecourse

This was one of the last outdoor events of the year and is run by the York Historic Vehicle group at the Knavesmire. We put on a Club stand for the second year running and had seven Sidevalves in attendance (photo 2). It stayed dry for the day but a cold wind swept across the site such that only the hardy types didn't have a good few layers on. The only thing I bought in the autojumble was a snow shovel in preparation for the winter!

Edinburgh Trial

Two hundred and thirty cars and bikes were entered for the 88th running of the Edinburgh Trial. The start was at Tamworth as in recent years, the sections scattered around Derbyshire, and the finish near Buxton.

Although it was dry and mild on the day, the preceding days had seen heavy rain and the sections were wet and muddy as a result.

The morning went well except for delays on the first two hills which were frustrating. Last



Photo 2

hill before breakfast was the double helping of Putwell which caused even more delays, partly due to ramblers and cyclists but also due to a difficult restart for the higher classes. Putwell B has always been rough but continues to get worse, and we crashed and banged to the top to find a severely bashed wheel rim which we drove on through to the breakfast halt (photo 3). There were many other tales at breakfast of bent rims and punctures on that section.

Bamford Clough soon loomed after breakfast with yet another long queue and many cars returning down after failing. Bamford is also getting rougher and I backed off shortly after the turning point for a particularly bad rock outcrop, then put my foot down. I know the car now has the power for Bamford but at that point the hill was very greasy and the resultant wheelspin soon put paid to our attempt. Anything getting past this greasy part went on to clear the hill: it was frustrating to find that our running partner David Child in his similar Ford Popular (but with lower gearing) just kept his foot down from the start, and cleared the greasy part and then the whole hill (photo 4). The frustration was further compounded when I bashed a rear wing trying to control the slide back down to the turning point.

A failure on a restart on the next section (in common with 95% of the entry) due to wet, shiny and polished rocks was the start of a slippery slope! The remaining sections were either



Photo 3

cancelled or a joke as they were mainly grass or mud by the time we reached them.

We finished the event three hours late, which was better than some who were up to six hours late. Our four failures were reduced to three in the results as one of the sections was not climbed by anyone in our class, or anyone in any class other than the top Specials one. This was still not good enough for an award. The results also showed that only five entries cleared all the hills that remained, demonstrating the difficulty of the trial this year.

The bent wheel has been treated to a large amount of heat to bend it back and the wing has been removed, bashed back into shape, repainted, and refitted ready for the Exeter trial in January. Why do I do it? Good question!



Photo 4

Regional News

North London

Robin & Jennie Thake

After a mixed show season when some large shows were cancelled due to bad weather, September improved, so the Sidevalve Holiday turned out fine (see report, right). On our return we had a very good show at Ramsey Rural Life Museum where we met up with Brian's group, which made it a good turnout. The following week we had arranged to meet up with Brian's group again at the Wood Green Animal Shelter but Jen found out there was a Grand Car Boot Sale on that day, so a call to Brian changed the venue to Hinchinbrooke Country Park. This turned out to be a good day with plenty of sunshine and a nice walk in the park and good company. Our last show of the season was at the Canvey Island Bus Rally with Andy, Richard and Shirley and ourselves. This was a good event with many classic cars on display and trips to the seafront in classic buses. Finally, to finish off the old cars events of a very wet year I went on my annual trip as a passenger in a 1903 Darracq on the veteran run from London to Brighton. Three hours of the five hour journey were completed in torrential rain and when I arrived back home Jen said, "did you get wet?" Reply: "!!!!YES!!!!"

As you will read in the holiday report the cars had a few problems, with David Heard's 103E losing a tooth in the gearbox, Richard breaking a clutch on his 103E, and a vibration on our E04A Anglia. All have now been put right with David replacing the parts in his gearbox, myself and Richard changing the clutch on his Pop, and myself changing the universal joint on the Anglia.

I have recently found the advantage of meeting other members and discussing problems. I met Tim Griffiths and was talking about soldering leaking carburettor floats, as I had tried on several occasions to re-solder them without success – when the float cooled off the float would collapse. He said to drill a very small hole in the float, then solder the main joint and allow to cool; then, with a soldering iron, seal the hole. I have now done this with success!

May I wish everybody a Happy Christmas and New Year and thank our group members for their support during the past year.

Sidevalve Holiday 2012

Jennie and Robin Thake

Our destination this year was Lowestoft so we could attend the Grand Henham Steam Rally at nearby Southwold.

We joined up with the Kent members at the show and after a little confusion on booking in we parked up and made a good display. As we started chatting David said that his car was playing up in 1st and 2nd gear and we had to admit that our car was a bit unwell with rumbling and vibration at certain speeds. We decided that neither problem was terminal but would investigate on our return home. We had a very enjoyable two days at the show with lots of exhibits and stalls we had not seen before. The kite flying was very impressive, particularly on the Sunday when there was more breeze with one chap flying three kites on his own. As Tim Brandon had joined us on the Sunday there was a total of eight sidevalves and one Humber on show, and we had a lot of interest and enquires about joining the club.

On Monday we decided to have a fairly quiet day so had a boat trip on Oulton Broad, just a couple miles from our hotel, and after a very pleasant trip and lunch we all went our separate ways for the afternoon. We and two other couples had a gentle stroll along the prom to Lowestoft Town Centre before meeting up at Hotel Victoria, just up the road from our B&B for an evening meal. We were made very welcome and decided to use this hotel for our evening meals for the rest of our stay. David and Lesley went home on the Monday afternoon and arrived safely back home in Hertford, and on investigation found that a tooth was missing from one of the gears.

On Tuesday Caister Castle and Motor Museum was our destination. We made a good sight in a convoy to the museum, parking up under the trees in the car park. Looking round the castle ruins was very relaxing, and after coffee we looked round the car museum where they are very strict on not putting a hand over the rope barrier! We did find a Model Y, Anglia



E04A. 100E Anglia and a 105E all lined up together.

Bressingham Garden Centre and Steam Railway with a Dad's Army exhibition was Wednesday's outing; we had a lift with Rob and Janet as our car was still not too happy and we all arrived safely after taking various routes. We had a good time looking round, riding the garden railways and gallopers and watching a Dad's Army film among the various scenes and memorabilia from the series. Richard managed to fall asleep during the film!

We were joined by Tim Brandon on our last full day on Thursday for a visit to Southwold, followed by a trip to the East Anglia Transport Museum on the outskirts of Lowestoft. The pier at Southwold has some very entertaining sideshows: don't let Robin near a Zimmer frame, and dog walking is not easy. On arrival at the Transport Museum which opened at 1pm we were welcomed by one of their members and directed to park up within the grounds on a pleasant grassed area. We kept the café in business and enjoyed the tram rides, train ride and even a trolley bus ride around the site, and did not leave until just before closing time.

After another very good evening meal and thank yous said, we chatted about our week and finally returned to our B&B for our last night there and our last enormous breakfast the following morning. We all arrived home safely despite the various problems we had had. Even our car seemed happier; perhaps it did not like staying in for the day? And so cars have been put away to await our next trip and repairs over the winter.



Regional Report

John Duckenfield

East Essex and South Suffolk

I am very pleased to report that following the resignation of John Hull, the Club's Regional Contact in Essex, John Gater has agreed to become the Regional Contact for Essex. It has to be said that he still has reservations about taking on the role but believes that, if no one else is willing to take it on, the Club is better being represented in the area by him than not at all. I am really grateful to him for trying and just wish that more members in other areas would follow his example. At the end of the day, if he finds that the job is not for him, so be it. At least he will have tried and I sincerely thank him for that.

John lives close to the county border and very much hopes that members living in south Suffolk would be interested in becoming involved. He is planning that come spring he can meet up on the occasional Sunday morning with fellow members at various locations. Further details will be in February's magazine but in the meantime, if you would like to find out more about what John has in mind, please contact him on 01206 240100. He would be delighted to hear from you – and for any help or support that you might be able to offer.

As John pointed out, there are plenty of members in the 'other' half of Essex to enable another group to meet in the south west of the county. All that is needed is a Regional Contact to make it happen! So please, if you live in that part of the world and would like to make a positive contribution to the Club, follow John's example and get in touch with me.



Back row, left to right: Geoff Hammond (Coventry and Midlands), Robin Barlow (Scotland – East), Glen Woolway, Richard Greenaway (Kent), Steve McKenna (East Lancs), Joe Wheatley (Merseyside and NW), Robert Marshall (Nottinghamshire), Tim Griffiths (Somerset), David Pickett (Sussex), Andy Main (Anglia, Prefect and Popular Registrar), John Duckenfield (Regional Co-ordinator). **Front row, left to right:** Ian Woodrow (Specials Registrar), Brian Cranswick (Cambs, Lincs and Norfolk), Nigel Hilling (Yorkshire), Martin Hatfield (North Yorkshire and Teesside), John Porter (FSOC Chairman), Robin Thake (London – North), Jennie Thake (Membership Secretary), Sally Litherland (Wiltshire), Danny Moody (Northamptonshire)

Annual Regional Contacts' Meeting

This year's meeting was held at The Welcome Centre, Coventry, letting Regional Contacts as far apart as Angus in the north-east of Scotland and Sussex in the south-east of England meet and discuss common issues, common problems and good practice.

More than that, though, it is a forum for raising issues to draw to the attention of committee members – often issues that are of concern to Club members within the Regional Groups. It is therefore an important link between the membership of the Club and Club officials and another means by which the voice of the membership can be heard. Conversely, it is also a valued sounding board for Club

officials whereby they can seek opinion from across the country about future decisions or current practices.

The meeting is an extremely informal gathering of like-minded, loyal and dedicated members of the FSOC. As the new classic car season rapidly approaches there is still the need for more Regional Contacts in several parts of the country. If your circumstances have recently changed, or you are a new member who would like to establish a Regional Group where you live by becoming an FSOC Regional Contact, please get in touch. The decision as to whether or not to proceed is yours. If you do, I honestly believe you would find it extremely enjoyable and rewarding.

A Word from Wilts

Sally Litherland

John Duckenfield is regularly asking all members to consider their commitment to the FSOC by becoming a Regional Contact, and you might wonder whether the time involved could outweigh the benefits. Think again! I have been the Wiltshire Regional Contact for a couple of years now but I am the first to admit that as a teacher, work has never allowed me to devote much time to the task – but that doesn't matter. Wiltshire is a large county and our delicious Sidevalves don't generally travel far, so any idea of a regular gathering is unlikely ever to happen here. Oh, and the small fact that despite having taken a car maintenance course in 1967, I am not technical! You see, this Club is your Club, our Club, and the delight we have in our cars (or bits of metal and engines yet to become cars) is a shared one. I put in as much or as little time as I have available. To start with, this was just an email address for Wiltshire members

to contact (they never did...). Now it is getting easier. The recent Regional Contacts Meeting in Coventry, so perfectly organised by John, brought together a wealth of knowledge and enthusiasm, so I am sure any problem you might have with your Sidevalve is something on which one of our members can advise. This isn't a sales pitch for you to sign up as a Regional Contact; however, it is a request for you to share more in the life of the Club. Send in your pictures, your problems or better still your solutions regarding your car. Use the website; order from our spares department and share your stories.

But now I must tell you about my 103E Molly's summer. It was heart-breaking. At the suggestion of an acquaintance I took her to a 'classic car' repairer in April. Initially they fixed her small incontinence problem within a week, but one mile from the garage the oil just poured out and she had to go back. After that they gave me all sorts of reasons why she could 'not be fixed yet'. I was away for most of the summer (celebrating retirement with a visit to my daughter in Australia) leaving the

garage with the one condition that she should be kept in a dry place because her roof leaked. When I returned in September she was still not back home, but after pestering she was brought back late one night in the dark. Next morning I could not start her and could see that she had been left out all summer. Her bodywork was spoiled, headlining stained and her beautiful red leatherette interior was splitting and damaged. I had to take her straight away to Graham Dimmer Motors who sympathetically fixed her broken choke cable and tightened up her engine mounting which had been left loose, plus so much more. Molly is 56 years old and has been with me for just over 30 years. This year she aged more than even L'Oreal can fix – and she is worth it. I'm sure none of that would have happened if I had first contacted my friends in the FSOC ...

So, members in Wiltshire – how was your Sidevalve summer? Let me know and let's put our county back on the map! Oh, and does anyone near Salisbury know a sympathetic classic car restorer? Molly needs a new vinyl roof.

Pre-War Register

Yvon Precieux

Registrar's comments

A good year for the register. The only gripe is that some members are not returning the register form, yet still asking me to identify their car! I have several registers in the pre-war section to keep up to date besides the E83W, so please return or update your vehicle information with the chassis, Briggs body number etc. It really does help. In the meantime I will be here next year so am wishing everyone a happy Christmas and the usual intoxicating New Year.

The Constabulary

We hear about our old Fords being used in all theatres of motoring. All those pundits that today just think of our cars as old have no idea what they were capable of. In this instance Model Ys, Model Cs/CXs, 7Y, 7W, Prefect and 100E models were used by various Police forces throughout the country from Scotland to Ireland to Gloucester, Manchester etc. The row of pre-war Sit-Up-and-Begs illustrated were from Fife constabulary and the Model Ys were used by the Garda, Eire. Proof that the cars could take on the rigours of hard driving on all sorts of roads, and capable of carrying equipment and the odd crook.

The Chester division also used the later models and one of their oldest models was a Model Y Popular of 1936. Police cars and their drivers were regularly inspected and inspections meant that personnel stood by their vehicles, usually for the Lord Lieutenant or other dignitary to pass alongside and comment. Yearly inspections were the norm and cars had to be spick and span as well as a well turned out driver. Tourers were also used, as sometimes it was easier to install the transmitters, some of which were of the Morse code variety. As with any electrical equipment, suppressors were necessary although there seemed to be no cure for a complete wipe out when the odd electrical tramcar passed by. Those were the days! (Photos 1, 2 and 3)

Those grille surrounds

The late Ted Broadhurst, who worked at Davis Bros, wrote this some years ago:

The chrome trim piece on the grille and some instrument panels fitted to our small Fords is in fact a stainless steel lead filled beading. It was made by a company called Davis Brothers (Motor Supplies) Ltd, Nightingale Grove, Hither Green in South East London, who also made the stainless steel fittings. Long lengths of stainless section were made on a draw bench, and then filled with lead. This was to permit bending to shape after cutting approximately to length. The final trim to length was after bending, to get a precise fit on to the radiator shell. The clips, which were actually brass bifurcated rivets, were installed by melting the



Photo 1



Photo 3

lead locally while the rivets were held in small jigs to keep them upright. After testing for fit on a shell grille the beading was sent to the polishing shop. In the early thirties, the lead filled beading was wide enough to take the normal head of a bifurcated rivet, but as the years passed and models changed, the beading became narrower and the round heads had to have the side cropped off to fit the narrower section.

A further change was also made to the method of making the joint. At first it was a butt joint, near the bottom reinforced with a piece of brass let into the lead like the rivets, but towards the end of the Model Y manufacture the joint encompassed a stainless steel clip at the bottom point.

Locally melting the lead with a very gentle flame, BOC Sapphire No. 1, a lead burning torch, or even a Bunsen burner, will release the remains of the broken rivets. They may be replaced with new rivets if a supply is readily available, but just as good and probably easier to position would be some small brass screws: about No. 4 or No. 6 ANF, or No. 5 or 6 BA would be suitable. A drop of soldering spirit on the heads helps before melting them in, and make sure that they are located upright by something more substantial than fingers.

The Briggs Manufacturing Company

Briggs Motor Bodies Limited was the UK arm of the Detroit Company of the same name and was a major partner with the Ford Motor Company at Dagenham, Essex. As a separate company it supplied Ford with bodies and at the same time also built bodies for other companies such as Austin, Riley and others during the pre-war period. After the war in November 1947, Briggs bought an old aircraft plant in Southampton, originally owned by Cunliffe-Owen Aircraft Ltd (now the Ford Transit factory). The latest news is that Ford will close this complex. This site was located at the southern edge of the then Eastleigh airfield. Briggs produced van and truck cabs and




Photo 2

bodies from a basic design with differences for Leyland, Dodge, Guy and Thames.

Towards the end of 1943, when the Second World War was well under way, the idea of founding a Lodge by members of the craft employed at Briggs Motor Bodies Ltd, Dagenham, was put forward by a Jack Worship. A number of the so called 'Brethren' in Briggs were contacted and eventually fourteen members of various Lodges attended a meeting held one evening (after office hours), when provisional arrangements for a committee was made. Various names for the Lodge were suggested and by a unanimous agreement, the name 'Lodge of industry' was decided upon. The 'Briggs' Lodge was established in 1945. The crest depicted the boiler house of Briggs Motor bodies at Chequers Lane with the annual subscriptions set at three and half guineas (£3.68) and the dining fee assessed at ten shillings (50p).

In May 1953 Briggs Bodies was acquisitioned by the Ford Motor company on express authorization from Dearborn (Henry Ford II) to secure body supplies and to ensure that Briggs did not fall into the hands of its competitor Chrysler, who had taken over the American parent company. The sale included the Dagenham, Southampton and Doncaster Briggs' plants. However it was stipulated that Briggs continue to fulfill its existing contracts with other companies. This meant that Briggs supplied truck cabs until late 1956.

Another off-the-cuff fact was that Redbridge FC, Essex, were, until the end of the 2003/04 season, Ford United FC, formed following an amalgamation in 1958 between Briggs Sports FC and Ford Sports FC. Briggs Sports were the works team of the Briggs Motor Bodies Company and played at Victoria Road, now home of Dagenham & Redbridge FC. Ford Sports however played at Kent Avenue in Dagenham, near to the Ford factory.

Working out the Briggs model sequence: one hypothesis

As with Ford's chassis numbers and certain vehicle codes, Briggs listed their bodies in a numerical sequence. As noted, the small Ford vehicle sequence commences at 121 and continues numerically into the pre-war Dagenham designed Fords and onwards to post-war. Although to many there appears to be no logic, there had to be some identification by Briggs to allocate the appropriate body to chassis to vehicle model. If one looks closely at

Model No	Model Name	Dates of Shipment		Quantity
		First Job	Last Job	
134	Y Fordor FR	22.09.32	30.08.33	2686
135	Y Tudor FR	4.07.32	11.05.34	22000
136	Y Fordor De Luxe	6.10.32	19.06.34	2209
164	Y Fordor FR	1.10.34	12.08.37	7965
165	Y Tudor FR	25.09.33	13.08.37	74360
166	Y Fordor SR	25.09.33	4.08.37	9135
167	Y Tudor SR	7.10.33	12.08.37	16883
362	C Tourer	2.05.35	20.01.36	1068
364	C Fordor FR	12.07.34	16.11.35	5023
365	C Tudor SR	8.10.34	20.08.35	5143
366	C Fordor SR	13.09.34	7.10.35	4634
367	C Tudor SR	14.09.34	6.11.35	2444
462	CX Tourer	25.01.36	1.03.37	1795
464	CX Fordor FR	14.10.35	19.03.37	8446
465	CX Tudor FR	1.11.35	15.04.37	11932
466	CX Fordor SR	28.11.35	7.04.37	4565
467	CX Tudor SR	28.11.35	17.03.37	2997
121	8 H.P. Van	14.11.32	7.06.33	1402
126	8 H.P. Van	12.06.33	22.11.33	1632
128	8 H.P. Van	22.11.33	5.11.37	26572
161	'A' Type Tug	16.09.35	24.09.37	121

Photo 4

the figure work, one can start to see some ideas that may be behind the coding for the earlier Fords such as the Model Y, C and CX, though major changes on the same lines as Ford's vehicle coding were required to be revised by 1937, when the UK and European Ford plants were manufacturing their many very different models.

The first two digits could be taken to identify body: 12 the Vans; 13 the Short Rad bodied cars; 16 the Long Rad bodied cars to include the Tug; and 36 and 46 the C and CX cars respectively. Looking at the third and final digit, this number could be taken in appearing to assist in the vehicle specification for example: 1 could be designated as something like commercial, 2 = tourer, 4 = fixed roof 4-door car, 5 = fixed roof 2-door car, 6 = 4-door spec variation, 7 = 2-door spec variation and 8 = cab variation. Have any members any further ideas on the subject? (photo 4)

Component Age

Our youngest vehicles in the pre-war register are over 70 years of age. Not bad for our Sidevalve Ford models, and more are still coming out of the woodwork. However some of us seem to forget that parts wear, with a majority ignoring the situation of metal fatigue. Whereas the first situation can be dealt with by proper periodical checks, metal fatigue is that more difficult to detect as today, such methods of crack testing etc. are now specialist, with the general hike-up in charges even if one can find such companies locally.

Stub axles are an example where most of us assume that such parts can continue to carry the loading and steering actions indefinitely, especially after constant use. Of note is that many of our vehicles have done over 100,000 miles, some twice over and more. You may have renewed the king pins and bushes regularly, but are you still using the original stub axles? Very robust these items are but one must not forget that initially when these cars were in use, a gauge as illustrated was developed to enable dealers to check the set of the front spindles in relation to any distortion due to an accident, collision or kerbing (photos 5 and 6).

Photo 7 photo illustrates what can happen to some of these older components. In this case it is a Model Y part with the straight arm. The Model




Photo 5




Photo 6



Photo 7

C and CX are similar but not identical and it was not until the later 7W and 7Y came along that Ford came up with the kinked arm type (circa Jan-March 1938) that is installed on all the later sit-up-and-begs. For those of you who are contemplating building a Special, I would recommend you use the later spindle body. You also have the safety of the track rod end being installed from the top as from the Model C onwards. On any independent suspension, strengtheners for the arms will be required, bolted to the back plate. If you use pre-war or post-war spindles, expect breakage at the arm as it connects to the spindle. What happens when the arm breaks when you are driving? Well, you will lose 70% control of your steering with the vehicle wanting to steer itself. Gentle hand braking is required while at the same time carefully feathering the steering wheel to keep the vehicle from veering systematically from side to side.

Another no go is not to mismatch the axle shafts when changing axles. In initial use they undergo a twisting action in the metal in one direction. Re-installing them, but changing the side they were originally matched, reverses their normal twisting action and they will fracture, usually at the juncture of wheel drum. Always label. Not so serious but still with metal fatigue is the bulkhead area of the Ford 103E around the spring for the accelerator and rod. After much use an area of 4"-6" square around the accelerator spring can flex. This reduces the lift at the carburettor, which means than when you



Photo 8

want full power, you will not get it. A plate to stiffen up this area will restore the appropriate lift at the carburettor direct to the action at the accelerator pedal.

An easy chair

Of all the seats in the small Ford range, the model C and CX bucket seats are in my opinion the best fitting as they contain both the passenger and driver of my van when I go round corners at speed. The tip-up seat versions I find dangerous as in an emergency stop they propel you towards the windscreen and the steering wheel. So, an advertisement for the Ford 10 with the seat advertised as an easy chair is a bit far-fetched. Mind you the back seat of all the old Fords are actually quite comfortable, especially when I have been lucky enough to just be the passenger, but those occasions are few and far between. (Photo 8)

Cylinder heads

For our newer members who wish to identify the engine in their vehicle, a letter or combination of a letter and numerals is used to signify an 8 or 10 engine. Normally it is a Y (8hp) or C (10hp) but earlier 8hp engine had a code 19E as the part number (post-late 1934) and early 8hp cylinder heads with the heart shaped combustion chambers had no detail at all. Even some C heads can be baffling with a 2 digit number. The peg or spigot type head was used on the Model Y, C, CX, 7Y and 7W. However, with the need to economise on metal, a new head was introduced with no spigot or platform to mount the dynamo. Instead a special separate pressed steel cradle was fabricated to mount the electrical equipment with the final aircraft platform type cylinder head being manufactured towards the end of 1945. Aluminium heads were around and available on all 8 and 10 engines from 1932, as indeed were the overhead valve conversions and remote gear control accessory items off the shelf. Nowadays one has to hunt for such specialist equipment.

E83W Register

Yvon Precieux

Registrar's Comments

I've survived another year in the post that I thought was temporary. It has been another good year, but again I would ask for the register forms to update the info for Club records. The restoration carried out has been to a very high standard and is remarkable considering the E83W was the workhorse of the day. Some interesting vehicles have come out of the woodwork and the special bodied van for transporting pianos has been quite a favourite. I'll endeavour to get through next year with your help and I thank Les, our Canada contact, and others for all their help during the year. Have a happy Christmas and again, as I am in Scotland, an intoxicating New Year.

Official Olympic vehicle

Did anyone else notice the article that Nigel Hilling saw in *Classic Car Buyer* that referred to the London Olympics in 1948? A fleet of E83Ws was the official transport for guests etc. and all were of the 'Car-o Van' 'Woodie' specification that could seat up to eight passengers, or six passengers with luggage. The young drivers were all female from the Auxiliary Territorial service, some with wartime service and all experienced in all sorts of driving. I am endeavouring to obtain a photo and permissions to use it in a future register page.

Restoration

Bob Deacon is currently restoring E83W registration OPL859. Bob would like any information on this vehicle.

Want to swap?

Shaun Adams-Thirtle has now finished the restoration of his Utilecon E83W. The vehicle has been shown in these pages at various times during restoration during the year. It looks the part now and, though a Utilecon is rarer than a van, Shaun is still keen on swapping the Utilecon for a van. So, does anyone out there want a swap? Shaun is your man to chat to. Enquiries through me. (Photos 1 and 2)

A past regret

Andy Cadell: Fifteen or so years ago my friend owned a Ford Thames E83W Utilecon, OBY362. The vehicle was original and in very good condition. We are wondering if it would be possible to be put in touch with the current owner? It would make an old man very happy, to know what the vehicle has been up to. Hope you can help. Many thanks.

The vehicle is still around and hopefully contact has been made –Yvon.

From the Archives

Photo 3 is interesting as, although seemingly just a front view of a pick-up, the notice in the window identifies it as a 'UTILEVAN' designed by Martin Walter. Photo 4 was taken at the LCC housing development in Picton Street, Camberwell in South London. The van seen outside this new housing scheme shows the E83W with quite a space between the two rear panel windows. It looks professional enough.

FYR 839

The ENSA (Entertainments National Service Association) had its headquarters at the Theatre Royal in Drury Lane, London during the Second World War. One area of the Entertainments aspect was the 'Sing-a-Long' section. The idea at the time was to use or recruit various theatre touring companies, rehearsed and managed by ENSA, to tour (in every sense of the word) the whole countryside in specially fitted vans. The smallest of the three types of vehicles used were the 8hp saloons, namely the more ancient Model Ys and 7Ys, with the larger vehicles being the Ford E83W and the Morris.

The Ford, being capable of carrying a heavy load, especially bore the brunt of the loaded equipment, which was stashed away very efficiently with every space allocated. A baby piano was positioned along one side of the E83W and along the other side was a set of seats for two of the 'Minstrels', of whom there were four. The other two occupied the passenger seat and the driver's position. A wardrobe was also accommodated for the various costumes and the numerous props were placed where they were out of harm's way – harm's way usually being on top of the piano and wardrobe.

Each of the entertainers was entitled to an attaché case and with the majority of cases bulging with added extras, these final additions made up the usual heavy load. Each touring company of four had to be quite versatile, unlike the 'entertaining' lot on TV these days. Not only had they to be masters of the song and dance, they had to be able to present short and snappy sketches. Drivers had to be skilled mechanics, or at least have some idea on making some of the older vehicles start, and make running repairs when minor breakdowns occurred. Many journeys were cross country, especially in the summer, and audiences varied from 10 to more than a thousand. Where there were just 10 spectators, this usually consisted of a searchlight crew and to reach them, the E83W in most instances had to cross ploughed fields with some undulating results as to the crew, the equipment and particularly the piano.

The number of shows per week per company usually averaged between 14 and 16 and the average number of airmen, sailors and army personnel was something like



Photo 1



Photo 2



Photo 3



Photo 4

1500. In the first 12 months of the scheme some 40 odd units were on the road, each covering some 42,000 miles. Individual vans were away for some nine months or more and the adventures of some of the E83Ws could probably fill a volume. During one foul winter, two E83W vans were lost for some seven days, totally snowed up, a far cry from situations today where individuals are freed

Continued on page 21



December 2012 Spares & Regalia Lists, Pop Shopper and Order Forms

Please keep this list safely as the Spares Lists will possibly not appear in all issues.

Note that all prices for FSOC regalia and spares include postage and packing for the UK only.

Minimum order £10.

Regalia List

Books

Reprint Workshop Manual for 5 and 10cwt vans, Anglia / Prefect 39-53,	
Popular 53-59.....	£18.00
Reprint Parts Manual for 5 and 10cwt vans, Anglia / Prefect 39-53,	
Popular 53-59.....	£18.50
Reprint Parts Catalogue, Y/C/CX/7W/7Y.....	£13.40
Reprint Model Y Bulletin.....	£12.50
Reprint Workshop Manual for 100E and 300E.....	£25.55
Reprint Parts Manual for 100E and 300E.....	£20.75
Technical Tips for the 100E/107E by Jim Norman.....	£8.30
100E Anglia and Prefect Instruction Book (1953-59).....	£9.90
The John Howe Book of Cartoons.....	£6.30
Ford Motor Cars, 1945- 64.....	£9.15
Ford Model Y, Henry's Car for Europe by Sam Roberts.....	£29.99
Ford Popular and the Small Sidevalves by Dave Turner.....	£20.99
Out In Front-The Leslie Ballamy Story by Tony Russell.....	£21.60

Stickers

Running In Instruction Sticker (Upright).....	£1.15
Running In Instruction Sticker (100E).....	£1.15
Running In Instruction Sticker: First 500 miles (100E).....	£1.15
Window Sticker-FSOC design.....	£1.06
Silver Jubilee Window Sticker.....	£1.06
Historic Ford-'Keep off My Arse!!' sticker.....	£2.05
I Love My Sidevalve Sticker.....	£2.05
Register Sticker (state model) each.....	£1.42
FSOC 30th Anniversary Sticker.....	£0.90
FSOC 40th Anniversary Sticker.....	£1.12

Magazines

Binder for Club Magazines (holds 2 years).....	£8.45
Following back copies of Sidevalve News available.....	£1.20
1990 April, June, August	
1994 December	
1995 February, April, June, October	
1996 February, April, October, December	
1997 February, April, August, October	
1998 February, April, June, August, October, December, with index for 1998	
1999 February, April, June, August, October, December, with index for 1999	
2000 February, April, August, October, December	
2001 February, April, August, October, December	
2002 February, April, June, August, October	
2003 February, April, June, August, October, December, with index for 2003	
2004 February, April, June, August, October, December, with index for 2004	
2005 February, April, June, October, December	
2006 February, April, June, August, December	
2007 February, April, June, August, October, December, with index for 2007	
2008 February, April, June, August, October, December, with index for 2008	
2009 February, April, June, August, December	
2010 February, April, June, August, October, December	
2011 February, April, June, August, October, December	
2012 February, April, June, August, October, December	

Leaflets

Ford Pop Motoring at Still Lower Price booklet.....	£1.90
Running in booklet Anglia / Prefect (date 9/49).....	£1.95

Models

Ceramic Cream Model of 103E Popular.....	£5.70
Limited Edition E494C FSOC 30th Anniversary Model.....	£19.99

Badges

Enamel Lapel Badges: FSOC, 103E or 100E.....	£2.15
103E Popular Cut-out Lapel badge (Black or Blue).....	£1.66
FSOC Grille Badge: Round or Square.....	£12.45
Register Grille Badge: Popular/Prefect/100E/107E.....	£12.50

Clothing

Please state size, design, colour and second choice of colour for all items of clothing.

FSOC black and red quartered rugby shirt embroidered in script	
SM/L.....	£25.25
FSOC Sweat Shirts embroidered in script.....	£16.20
<i>Racing Green or Raspberry SM; Burgundy or Royal Blue XXL;</i>	
<i>Navy in Med/XXL; Red or Sky Blue in Med/L/XL/XXL; Black in Med/L/XXL</i>	
FSOC Polo Shirts embroidered in script.....	£14.60
<i>Lemon, Sky Blue or Emerald in SM</i>	
New FSOC Sweat Shirts embroidered with FSOC logo.....	£16.50
Royal Blue only in Med / L / XL	
New FSOC Polo Shirts embroidered with FSOC logo.....	£13.90
<i>White or Royal Blue in Med / L / XL only</i>	
New FSOC Sweat Shirt and Polo Shirt embroidered with FSOC logo.....	£27.90
Royal Blue Sweatshirt with either Royal Blue or White Polo shirt Med / L / XL	

T-Shirts

Model designs.....	£9.50
<i>E83W picture printed on front in Red or Black XL</i>	
<i>Upright picture printed on front in White L/XL</i>	
Script Badge Design.....	£8.60
<i>Ford Popular: Green, Black, Red, White, Royal Blue or Navy in SM only</i>	
<i>Ford Prefect: Yellow, Navy or Green in SM/MED; Red SM; Royal Blue MED</i>	
<i>Ford Anglia: White or Yellow in SM only; Green, Royal Blue, Navy or Red in SM/MED, Black MED</i>	

Other Regalia

Licence Disc Holder.....	£1.05
Blue FSOC Mug.....	£4.85
DVD of Ford Archive material and FSOC events.....	£5.95
FSOC 40th Anniversary Beer Glass.....	£20.75
FSOC 40th Anniversary Beer Tankard.....	£23.50
Tea Towel, All models design.....	£4.50
Leather Keyfob; Popular / Anglia / Prefect (please state which).....	£2.85
FSOC Woven Tie.....	£7.95
Xmas cards (pack of 5 different designs).....	£3.50
Dusters: Yellow duster printed with various sidevalve models around border, Club logo in Centre	
Per duster.....	£2.45
Pack of two dusters.....	£4.50
Pack of three dusters.....	£6.00
Gift Vouchers (can be exchanged for Regalia, Spares or Membership).....	£5.00

100E and 107E Spares List

Front Brakes

100E-2018	Front brake shoes 7" diameter, set of four (for vehicles up to Jan 1955, old shoes must accompany order).....	£29.95
100E-2018-C	Front brake shoes 8" diameter, set of four (Feb 1955 onwards, old shoes must accompany order).....	£35.00
100E-2035	Front shoe return spring kit (axle set).....	£10.95
100E-2038	Adjuster repair kit (front).....	£16.00
100E-2061-B	Wheel cylinder 1957 onwards right hand side.....	£12.50
100E-2062-B	Wheel cylinder 1957 onwards left hand side.....	£12.50
100E-2062-A	Wheel cylinder pre 57 left hand side (exchange £10 surcharge *).....	£35.00
100E-2061		
/ 02062-B	Wheel cylinder repair kit 1957 onwards per axle set.....	£7.25
E0A-2078	Hydraulic flexi hose.....	£13.25
100E-2140	Master cylinder.....	£72.00
100E-2185B	Master cylinder retainer.....	£4.50
E66-Z-1	Master cylinder repair kit.....	£12.50

Rear Brakes

100E-2041-B	Snail cam (shoe adjuster).....	£0.75
-------------	--------------------------------	-------

100E-2075	Connector (5 way brake pipes).....	£12.25
	Rear shoe return spring.....	£6.00
	Rear brake spring (set of 4).....	£22.00
100E-2103	Late hand brake lever.....	£14.00
100E-2119-B	Compensator (hand brake cable).....	£5.20
100E-2220-A	Rear brake shoes 7" diameter (up to Jan 1955, old shoes must accompany order).....	£29.95
100E-2220-C	Rear brake shoes 8" diameter (Feb 1955 onwards, old shoes must accompany order).....	£29.95
100E-2261-B	Rear wheel cylinder 7" (53-55).....	£14.00
100E-2261-C	Rear wheel cylinder 8" (55-57) Reconditioned exchange only-old unit must accompany order.....	£22.00
	Wheel cylinder repair kit per axle set (fits 261B, C and D).....	£7.00
100E-2295-B	Hand brake cable.....	£32.50
100E-2857B	Hand brake clevis.....	£1.50

Steering and Front Suspension

E55-DB1	Top suspension mount.....	£40.00
E55-DB1	Pair top suspension mount.....	£75.00
E55-DB1	Pair top suspension mounts and 2 sets mount bearings.....	£110.00

Please note that all our prices include postage and packing! (for UK members only)

	Mount bearings per side-2 x E 38- DB1	
	plus 2 x E 37-DB8	£23.00
	Suspension insert	£65.00
	Suspension insert plus top suspension mount	£99.00
	Pair suspension inserts	£120.00
	Pair suspension inserts plus pair top suspension inserts	£190.00
100E-1190	Hub seal 0.983"	£7.00
105E-1190	Hub seal 1"	£7.00
Y-1202	Hub bearing inner 0.983"	£30.00
E-20-LB-1	Stud and bush.....	£15.00
100E-3063	Bushes per set (track control arm / cross member)	£7.00
100E-3073	Track control arm repair kit.....	£16.00
100E-3078-C	Track control arm right hand (exchange £10 surcharge *)	£27.50
100E-3289/90-B	Pair track rod ends	£30.00
100E-3304	Drag link (exchange £10 surcharge *).....	£59.00
100E-3591B	Steering box oil seal (early and late models)	£7.25
	Front suspension bush kit - 4 x E-10-DB- and 8 x 3063	£25.00

Rear Axle

100E-1107	Wheel stud	£2.50
100E-1175	Rear hub seal, original material	£12.25
100E-1175	Rear hub seal, modern neoprene	£7.00
E493A-4050	Retainer (rear axle shaft grease)	£7.30
100E-4209	Crown wheel and pinion.....	£80.00
100E-4235	Half shaft.....	£30.00
100E-4676	Pinion seal, 100E only	£7.00
100E-4851	Flange (propshaft).....	£18.00
100E-5713	Bar rear spring shackle-inner.....	£5.00
100E-5719	Bush rear spring shackle (set of 4).....	£7.25
100E-5781	Rear spring eye bush.....	£6.50
100E-5781	Pair rear spring eye bushes	£11.00
100E-7091	Yoke (propshaft)	£12.00
100E-18080-A	Shock absorber.....	£40.00
E-7ED-1	Rubber bush (bottom shock) (2).....	£3.00

Exhaust

100E 5250/5225/ 5255	100E mild steel exhaust system.....	£138.00
100E 5250/5225/ 5255	100E stainless steel exhaust system	£235.00
Y-5251	Manifold to exhaust clamp with stainless steel bolts and brass nuts.....	£9.95
	100E exhaust fitting kit.....	£22.50

Engine Parts

100E-6038	Engine mount.....	£30.85
	(exchange £10 surcharge*-remove rubber from mount)	
100E-6051-B	Head gasket.....	£19.95
100E-6102	Piston set (std, +0.010",+0.020",+0.030", +0.040")	£200.00
100E-6149	Piston ring Set (std, +0.020",+0.030", +0.040").....	£65.00
E93A-6270	Timing Chain	£17.99
100E-6308	Crankshaft thrust washers (per set) std, + 0.025"	£13.50
100E-6331	Main bearing set (std, -0.010",-0.020",-0.030",-0.040", -0.060")	£41.00
100E-6347	Packing Seal Crankshaft Rear (set of 2).....	£4.00
100E-6521	Gasket valve chamber cover.....	£5.00
100E-6505	Exhaust valve.....	£7.50
100E-6505	Exhaust valves (per set of 4)	£26.00
100E-6507	Inlet valves (per set of 4)	£20.00
100E-6513	Valve springs (per set)	£15.00
100E-6714-B	Oil filter element.....	£5.00
100E-6763B	Oil filler tube.....	£15.00
100E-9278	Oil pressure switch	£7.50
100E-9448	Manifold gasket, 100E only.....	£2.50
	Manifold stud.....	£4.95
E55Z1	Conversion gasket set	£27.00
E81Z1	Decoke gasket set	£27.00
353000ESA	Core Plug	£2.50
	Big end bearing set (std, -0.010",-0.020",-0.030",-0.040", -0.060")	£29.50
	Small end bushes (set of 4).....	£23.50

Clutch and Gearbox

EOA-2078E	Flexi hydraulic hose.....	£13.00
E266-GD-1	Slave cylinder, 100E only (exchange £10 surcharge *)	£32.00
E149-Z-1	Slave cylinder repair kit, 100E only	£4.00
100E-2140	Master cylinder.....	£72.00
E66-Z-1	Master cylinder repair kit	£12.50
E74-7580-A	Release bearing.....	£14.50
100E-6068	Gear box mounting fits 100E and early 107E.....	£24.95
100E-7039	U / J repair kit	£13.95
100E-7052	Front oil seal	£7.00
100E-7086	Gasket tail shaft housing.....	£1.80
100E-7111	Counter shaft.....	£31.00
100E-7114B	Gear and bush assembly	£25.00
Y-7119	Washer (counter shaft gearbox thrust).....	£6.32
100E-7223	Gearbox lid gasket	£0.90
100E-7550-C	Clutch driven plate, 100E only (exchange £10 surcharge *)	£30.00
100E-7657	Rear oil seal	£7.00

100E-7569	Clutch pressure plate, 100E only (exchange £10 surcharge *).....	£52.50
100E-17286	Ring speedo gear retainer	£1.00

Cooling System

EOA-8100	Radiator cap, fits 100E and 107E.....	£4.99
100E-8115	Radiator drain tap (not original)	£3.50
100E-8260A	Early top radiator hose, 100E only.....	£15.40
100E-8260B	Late top radiator hose, 100E only.....	£12.80
100E-8275	Water inlet tube.....	£13.90
100E-8286	Bottom radiator hose, 100E only.....	£12.90
100E-8501	Water pump, 100E only (old unit must accompany order)	£55.00
100E-8507	Water pump gasket.....	£3.00
116E-8575	Thermostat	£6.50
EOTA-8620-C	Fan belt, 100E only.....	£6.00

Fuel System

	Fuel pump with spacer (no primer).....	£43.50
	Petrol filler grommet.....	£12.50
100E-9276	Gasket (fuel tank sender).....	£1.25
100E-9288	Flexible fuel pipe	£15.80
100E-9437	Hot spot gasket	£1.95
100E-9627-A	Rubber (air cleaner).....	£7.25
100E-9959	Gasket carburettor float chamber	£1.45

Electrical

EOTA-10001- B	Dynamo, not Popular (exchange £10 surcharge *)	£65.00
105E-10001- B	Dynamo, Popular only (exchange £10 surcharge *)	£43.00
105E-10043	Brush set	£4.75
E274-CQ-1	Pinion (starter motor drive)	£11.00
100E-10505-B	Voltage regulator (push on terminals)	£35.98
100E-11001-C	Starter Motor (please send old unit with order)	£45.00
105E-11057	Brush set starter motor.....	£3.75
204E-13007A	Headlight bulb pre focus 40 / 50 watt	£5.99
	Stop/tail bulb, 12v, 21/5 watt.....	£2.99
100E-13450B	Rear light lens, red.....	£14.95
300E-13450	Rear light lens, red.....	£14.95
E0A-13480	Brake light switch	£6.50
E1050-NC-1	Rear red tail light lamp with rear lamp gasket for Anglia Prefect 1957 onwards includes fixing screws.....	£15.75
100E-134641-C	Pair of rear red tail light lamp lenses	£26.50
50563-S		

Ignition System

100E-12029	Set 100E ignition leads	£14.95
7V-12098	12v Ignition coil.....	£42.95
	Nut H.T. lead distributor cap (set of 5)	£3.00
	D type distributor only (rebuilt-exchange £10 surcharge)	£50.00
	Round type distributor only (rebuilt-exchange £10 surcharge)	£50.00
	Distributor cap (D type).....	£25.00
	Distributor cap (round type)	£14.75
	Contact set (D type distributor only).....	£15.20
	Contact set (round type distributor only)	£15.20
	Rotor arm	£5.25
	Condenser (D type distributor only).....	£9.60
	Condenser (round type distributor only)	£9.60
	Spark plug.....	£3.70

Badges

100E-16185 / 9	Triangular wing motif.....	£15.25
E6AJ-1	Prefect boot script.....	£15.25
100E-16606	Prefect bonnet	£15.25
E5AJ-1	Anglia boot script	£15.25
100E-16606	Anglia bonnet	£15.25
100E-16606-G	Popular bonnet	£15.25
100E -7042514	Popular boot script.....	£15.25
100E-16850	Bonnet 'V' motif.....	£35.50
	Deluxe boot script.....	£15.25

Miscellaneous

E40GB1	Gear lever gaiter	£25.50
100E-17262	Speedo cable	£21.50
100E-7029744	Rear side window rubber per side (2 door model).....	£15.50
100E-7042084-B	Rear screen rubber-deluxe only	£29.95
EOA-732003-B	Floor grommets-per set of four.....	£5.15
100E-7322610	Interior door handle	£8.95
	Stainless steel locking petrol cap.....	£14.95

107E Specific Items

105E 42A8B	Rear hub oil seal, 107E only	£7.00
105E-4676B	Pinion oil seal, 107E only.....	£7.00
107E-6020	Timing chain cover gasket.....	£2.50
	105E oil filter.....	£6.50
E72-Z1	Clutch slave cylinder kit, 107E only	£4.00
105E-7550C	Clutch driven plate, 107E only (exchange £10 surcharge *)	£26.00
105E-7563D	Clutch pressure plate, 107E only (exchange £10 surcharge *)	£52.50
107E-8260	Top radiator hose, 107E only.....	£10.75

Please note that all our prices include postage and packing! (for UK members only)

107E-8286B	Bottom radiator hose, 107E only.....	£12.50
105E-8501	Water pump, 107E only.....	£40.00
105E-8620	Fan belt, 107E only.....	£5.75
105E-9448	Manifold gasket, 107E only.....	£2.00
107E-9959B	Float chamber gasket.....	£2.00
105E-12116	Distributor cap (round type).....	£14.75
EOTA-12199-C	Contact set (round type distributor only).....	£15.20
105E-12300-A	Condenser (round type distributor only).....	£6.50
105E-10043	Brush set.....	£4.75
105E-11057	Brush set starter motor.....	£4.75
353000 ES	Core plug, 107E only.....	£2.50

Spares List for 8 & 10hp Type Models

Rear Axle

Y-1175-A	Retainer (Rear wheel grease) assembly.....	£7.20
B-1175	Rear Wheel Retainer (fits E83W).....	£7.05
48-1190-A	Retainer (front wheel grease) assembly.....	£5.85
7W-1225-B	Rear Hub Bearing including race (fits all models except Models Y,C and E83W).....	£76.50
68-1225-A and 68-1236-A	Rear Hub Bearing including outer race (fits E83W only).....	£66.50
	Rear Wheel Bearing Kit (fits all models except E83W).....	£160.00

Braking System

YE-2019A }	Brake Shoes (set of 4-all models- exchange £10 surcharge).....	£55.50
CE-2019B }		
7W-2019 }		
Y-2035		
Y-2035		
7W-2035		
7W-2035		
E83W-2035		
E83W-2035		
Y-2036		
7W-2116	Front Brake Dust Covers (pair, fits all models except Models Y and C).....	£8.50
7W-2205	Rear Brake Dust Covers (pair, fits all models except Models Y, C and E83W).....	£13.20
E93A-2248	Rear axle brake plate securing bolts, long (each).....	£5.99
7W-2249	Rear axle brake plate securing bolts, short (each).....	£5.99
Y-2454	Brake Pedal (exchange-remove rubber from old pedal and send with order).....	£13.85
	Brake pedal return spring.....	£6.25
E83W-2498A/B	Rear Brake Cables (Pair E83W).....	£69.95
E83W-2580/1B	Front Brake Cables (Pair E83W).....	£22.76
7W-2580/1/4/5	Set of Brake Cables (not E83W).....	£60.95
YE-2793	Spring (handbrake lever pawl).....	£0.85
7W-2853C	Hand Brake Cable (fits all models except Models Y, C and E83W).....	£24.95
	Hand Brake Cable Clevis Pin.....	£2.00
E83W-2853B	Hand Brake Cable (fits E83W).....	£27.40

Steering and Suspension

Y-3030	Bolt (front axle to radius rod Model Y).....	£25.00
CE-3030B	Bolt (front axle to radius rod, not Model Y & E83W).....	£38.50
E83W-3032	Bolt (front axle to radius rod E83W).....	£24.50
E93A-3290	Track Rod Ends (pair)all saloons and 5cwt vans.....	£65.00
	Track Rod Ends (pair) E83W.....	£60.00
YE-3304C	Draglink (Y model).....	£72.75
E493A-3304	Draglink (C, 7Y, 7W, Anglia, Popular, Prefect, 5cwt vans).....	£67.50
YE-3332	Trackrod End Dust Cover (each, fits all models).....	£3.90
YE-33111	King Pin Set, complete (Model Y).....	£70.00
CE-33111	King Pin Set, complete (Model C).....	£70.00
7W-33111	King Pin Set, complete (7Y,7W, Anglia,Popular,Prefects,5cwt vans).....	£79.95
E83W-33111	King Pin Set, complete (E83W).....	£59.00
7W-3590-A	Arm(steering gear) fits models 1937 to 1949.....	£20.00
Y-3446	Front axle A-frame Bush (fits all models).....	£5.85
YE-3616B	Horn Button and Nut (Y model).....	£7.80
E93A-4020	Shackle Bush (metalastic type) saloons and 5cwt vans 1946 onwards.....	£7.65
E93A-4020	Shackle Bush (metalastic type) saloons and 5cwt vans 1946 onwards (set of four).....	£21.00
E493A 4050	Retainer (rear axle shaft grease).....	£7.30
Y-4217	Bolt (diff gear case).....	£3.30
18-4217	Bolt (diff gear tube).....	£4.60
Y-4507	Gasket (torque tube to differential housing cap).....	£1.75
7W-4507	Gasket (torque tube to differential housing cap).....	£1.75
Y-4515	Gasket (universal joint housing cap).....	£1.69
E93A-4607	Pin (Drive Shaft).....	£2.09
Y-4615-B	Bearing (drive pinion) assembly Model Y.....	£15.00
Y-4636	Lock Washer (pinion bearing nut) all models except E83W.....	£2.55
Y-4637	Thrust Washer (pinion bearing)	

	all models except E83W	£1.95
Y-4655	Torque tube bearing sleeve	£9.95
E93A-18055A	Front Shock Absorber Link to fit E493A, E494A & 103E	£20.00
E93A-18055B	Rear Shock Absorber Link to fit E493A, E494A & 103E	£20.00
E83W-18055B	Front Shock Absorber Link to fit E83W	£25.00
6E-18055B	Rear Shock Absorber Link to fit E83W	£25.00
	Shock absorber (specify which one required)	£85.00
	Front wheel bearings (wheel), not E83W	£56.00
	Front wheel bearings (per axle set), not E83W	£110.00
	Front wheel bearings (wheel), E83W	£56.50
	Front wheel bearings (per axle set), E83W	£110.50
	Suspension Buffer (fits all models except Model Y)	£15.99

Exhaust Systems

E93A-5255-C	Model Y stainless steel exhaust system.....	£117.00
	5 cwt stainless steel exhaust system.....	£111.00
	E83W stainless steel exhaust system.....	£106.50
	E93A-5230/Prefect and 7W stainless steel exhaust system.....	£199.00
E93A-5230 / E04A-5255-B Y-5251	Anglia, 103E and 7Y mild steel exhaust system.....	£170.00
	Manifold to exhaust clamp.....	£9.95

Engine Parts

E493A-18666-A	Pipe (cleaner outlet) assembly and	
E493A-18666-B	Pipe (cleaner inlet) assembly.....	£45.20
E93A-18670	Oil Filter Unions (pair) (fits all engines).....	£12.95
Y-6038	Front Engine Mounting (exchange and send both parts with order – remove rubber from mount).....	£9.99
	Front Engine Mounting bolt.....	£0.95
E93A-6250A	Camshaft (Chain Driven).....	£62.75
E93A-6258	Retainer (camshaft sprocket) chain driven camshaft.....	£3.15
E93A-6270	Timing Chain.....	£17.99
YE-6280A	Washer (camshaft thrust) all engines from 1936 onwards.....	£3.50
CE-6310	Crankshaft Oil Slinger.....	£1.85
E93A-6310	Crankshaft Oil Slinger.....	£1.90
Y-6384	Starter Ring Gear (fits all engines).....	£47.95
E93A-6510B	Valve guide (per split guide).....	£23.00
	Valve guide (per set).....	£169.50
CE-6505A/B	Short Length Valve (exhaust and inlet available).....	£7.00
E93A-6505F	Long Exhaust Valve (Can also be used as inlet).....	£14.95
Y-6513	Valve Springs (set of eight) (fits all engines).....	£22.50
Y-6520	Valve Cover (fits all engines).....	£15.95
Y-6560	Drive Bush (oil pump and distributor) (fits all engines).....	£4.97
Y-6561	Drive Sleeve (oil pump and distributor drive gear) (fits all engines).....	£4.09
Y-6566	Dowel (oil pump and distributor drive gear bush) (fits all engines).....	£2.15
Y-23670	Pin (oil pump drive gear to sleeve) (fits all engines).....	£0.86
Y-6610B	Oil Pump Gear (fits all engines).....	£4.85
YE-6623	Oil Pump Screen (fits all engines).....	£9.77
	Stainless steel dip stick tube.....	£29.75
	Main Bearing Set (std, -0.010",-0.020",-0.030",-0.040", -0.060") (fits all engines).....	£55.00
	Pre-War Piston Sets (8hp and 10hp, limited sizes only).....	£40.00
	E93A 10hp Piston Set including rings (std, +0.010",+0.020",+0.030", +0.040").....	£205.00
	E93A 10hp Piston Ring Set (std, +0.020", +0.030", +0.040").....	£43.00
	3-Ring 10hp Piston Ring Sets (+0.010", +0.020").....	£20.00
	8hp decoke gasket set (1932-34).....	£35.00
	8hp decoke gasket set (1935-1953).....	£45.00
	10hp manifold gasket.....	£7.25
	Manifold stud.....	£4.95
	Manifold stud (set of 4).....	£18.80
E15-Z-1	Decoke gasket set (E93A 10hp engine).....	£29.95
	Conversion gasket set (E93A 8hp and 10hp engine).....	£29.95
	10hp cylinder head gasket.....	£19.95
YE-24052C	Studs (Cylinder head) set.....	£34.99
	Set nuts for cylinder head studs.....	£4.00

Clutch and Gearbox Parts

Y - 2454	Clutch Pedal (exchange-remove rubber from old pedal and send with order).....	£13.85
Y-5102	Gearbox Rubber Mounting (Y & C models only).....	£38.50
	Gearbox Mount Upper (not Model Y or Model C models).....	£9.95
	Gearbox Mount complete, per side.....	£20.95
Y-7015	Main Drive Gear (8hp).....	£35.75
YE-7015	Main Drive Gear (10hp).....	£38.50
Y-7040	Baffle (main shaft gear bearing oil)-rear.....	£1.25
7W-7050	Retainer (main drive gear bearing).....	£17.50
7W-7052	Seal (main drive gear bearing oil) assembly.....	£4.60
YE-7059B	Mainshaft and Bush.....	£35.50
Y-7065	Bearing (main shaft) drive gearball assembly.....	£21.95
Y-7069	Washer main shaft intermediate gear thrust.....	£7.50
E04A-7070	Retaining Ring (snap ring).....	£1.55

Please note that all our prices include postage and packing! (for UK members only)

YE-7071B	Washer intermediate gear thrust washer.....	£7.60
	Baffle (main shaft oil)-front.....	£1.25
E93A-7085	Rear Bearing Retainer.....	£19.75
Y-7086	Gearbox rear gasket.....	£4.50
Y-7111	Layshaft.....	£41.65
103E-7114	Counter Gear (10hp).....	£46.95
Y-7119	Washer (Counter shaft gear thrust).....	£6.32
CE-7141	Reverse Gear.....	£29.95
YE-7222	Selector Housing.....	£19.05
Y-7223	Gearbox lid gasket.....	£2.50
Y-7523	Clutch return spring.....	£5.90
7W-7533	Clutch linkage clevis pin.....	£2.15
Y-7550	Clutch Plate-All models, except E83W (exchange and send with order).....	£29.50
YE-7563B	Clutch Cover – All models, except E83W (exchange – send with order).....	£62.00
E83W-7563	E83W Clutch Cover (exchange-send with order).....	£66.00
E74-7580A	Clutch release bearing-All models.....	£14.50
E70-7600-A	Clutch Pilot Bearing.....	£6.35
C-943070	Gear Lever Gaiter (except E83W).....	£19.60
E83W-943070	E83W Gear Lever Gaiter.....	£19.99

Cooling System

E0A-8100	Radiator Cap (pressure type for 103E and some E493As).....	£4.99
Y-8109	Radiator cap (brass screw type).....	£6.99
Y-8260	Radiator Hose (reinforced, straight for pre-war engines, top).....	£5.20
Y-8260 / 8286	Radiator Hose (reinforced, straight for pre-war engines, bottom).....	£4.95
	Radiator Hose (moulded-E83W, top).....	£19.05
E83W-8286	Radiator Hose (moulded-E83W, bottom).....	£19.50
	Radiator Hose (moulded-bottom).....	£17.40
	Radiator Hose (moulded-top, pressurised radiator cap.....	£16.95
	Radiator Hose (moulded-top, brass non-pressurised radiator cap).....	£15.60
E493A-8501	Reconditioned export water pump (exchange only – send with order).....	£150.00
	Water Pump Repair Kit.....	£32.50
E493AFS-8509	Pulley (water pump).....	£35.00
YE-8606B	Fan Blade (11").....	£7.90
E494A-8610	Pulley (fan and generator 4.12" O.D.).....	£9.50
E93A-8620-A	Fan Belt (late 8 and 10 hp engines without waterpump).....	£7.95
E493AFS-8620	Fan Belt (late 8 and 10 hp engines with export waterpump).....	£7.99

Fuel System

	Fuel Pump with spacer (no primer).....	£43.50
	Fuel Pump repair kit.....	£27.45
	Fuel pump stud.....	£6.35
	Fuel pump stud (set of two).....	£10.60
E04A-9080	103E/E494A Petrol Filler Grommet.....	£12.95
7W-9080	7W / E93A / E493A Petrol Filler Grommet.....	£10.85
BE-9288-A	Flexible Petrol Pipe (except E83W).....	£15.35
YE-9355	Fuel Pump Cover (all models).....	£1.97
YE-9364-B	Gasket (fuel pump screen cover).....	£0.65
YE-9365	Fuel Pump Cover Screen (all models).....	£1.50
YE-9374	Gasket (fuel pump to cylinder).....	£0.95
7W-9425	Inlet Manifold (10hp).....	£17.00
YE-9435	Gasket (inlet manifold to exhaust manifold "hot spot") (all models).....	£3.10
YE-9448	8hp manifold gasket.....	£7.50
	Rebuilt 8 hp Carburettor (exchange-send with order).....	£82.00
	Rebuilt 10 hp Carburettor (exchange-send with order).....	£87.50
Y-9447	8hp Gasket (carburettor to inlet manifold).....	£1.27
CE-9447	10hp Gasket (carburettor to inlet manifold).....	£1.30
YE-9502	Carburettor Gasket Kit.....	£7.95
YE - 9555	Carburettor Float (all models).....	£4.50
YE-9660	Connector (Starter Valve) Assembly.....	£6.00
48-9735	Accelerator Pedal (all models except Y,C and E83W).....	£13.95

Ignition System

	Emergency breakdown kit comprising points, plugs, roto, Condenser, fan belt and distributor cap (1935 onwards).....	£60.00
	Set E93A ignition leads.....	£14.95
E83W 12024A	6V Ignition Coil (All models-not original).....	£39.75
YE-12100B	Distributor-rebuilt (exchange-send with order).....	£50.00
YE-12116B	Distributor Cap (All models 1935 onwards).....	£13.50
YE-12185B	Toggle (All models 1935 onwards).....	£0.62
YE - 12191B	Spring (distributor weight) no 1 - light.....	£2.85
YE-12199B	Contact Set (All models 1935 onwards).....	£15.20
YE-12200C	Rotor (All models 1935 onwards).....	£5.25
YE - 12242-B	Spring (distributor weight) no 2 - heavy.....	£1.28
YE-12300B	Condenser (All models 1935 onwards).....	£9.60
52-12405A	Spark Plug, L86C (All models also 100E).....	£3.70

Electrical System

	Dynamo-2 brush, early type (exchange-send with order).....	£89.50
E494A-10001	Dynamo-3 brush, early type only (exchange-send with order).....	£110.00
E494A-10001	Dynamo-3 brush, late type only (exchange-send with order).....	£89.50
YE-10094	Bearing (generator drive end) assembly.....	£5.95
YE-10160	Felt (dynamo drive end bearing).....	£0.85
7W-10505	Cut out assembly (rebuilt, for use with 3 brush dynamo,	

	exchange only.....	£25.95
E93A-11001	10hp Starter Motor rebuilt (exchange-send with order).....	£115.00
YE-11001C	8hp starter motor (exchange-send with order).....	£115.00
7W-11359	Spring (starter pinion retaining).....	£0.98
BE-11450	Starter Switch.....	£18.00
E493A-13007	E493A Pre Focus 30W/24W Bulb (E493A Prefect only).....	£3.90
E493A-13007	E493A Pre Focus 45W/35W Bulb (E493A Prefect only).....	£5.70
ET6-13007-B	Headlamp Bulb 36W/36W.....	£6.20
7V-13061	Retaining Clip ("W" clip) (holds headlamp lens in rim for E83W).....	£0.75
CE-13061	Retaining Clip ("W" clip) (holds headlamp lens in rim for 103E).....	£0.75
E493A-13068	E493A Gasket (headlamp lens to door dust excluder) (E493A Prefect only).....	£4.00
YE-13081	Spring (front sidelight socket 1934 onwards except E493A).....	£0.62
CE-13101	Spring (headlamp focusing).....	£0.70
E93A-13130	E93A/E04A headlamp rubber base pad (pair) (E04A and E93A only).....	£25.00
103E-13408B	103E Plate Rear lamp base (pair).....	£41.50
103E-13420/1	103E Rear Lamp Rubber Base Pads (pair).....	£18.99
103E-13450/1	103E Rear Lamp Lenses (pair).....	£29.99
	E493A refurbished number plate lamp.....	£70.00
ET6-13465	Stop/Tail Bulb 6V 21W/5W index pin (straight pin also available).....	£3.05
40E-13466	Panel bulb 6V 3W.....	£3.60
78E-13466	E493A Sidelight Bulb 5W MBC (E493A Prefect only).....	£2.95
BE-13466-A	Sidelight Bulb 5W CC (not E493A).....	£2.99
E83W-13550B	Popular no. plate lamp (E83W and 103E only).....	£21.75
CE-13740A	Toggle Switch (panel lamp).....	£10.60
38193-57	Headlamp mounting bolts plus nuts (each).....	£9.99
	Model C Semaphore Direction Indicator (6volt only) (exchange only).....	£99.00
E04A-118004B	Semaphore Direction Indicator (6volt only) (exchange only).....	£65.00
E04A-118004B	Semaphore Direction Indicator (6volt only) (no exchange).....	£95.00

Rubber Grommets and Seals

E68-AD-1	Fixed side window rubber (per ft) (saloons 1937 onwards).....	£1.99
7W-16625	7Y, E04C, E494A, E494C, 103E Bonnet Corner Pads (pair).....	£4.95
	E83W Bonnet Corner Pads (Pair).....	£11.99
	E83W Bonnet Corner Pads (Full set).....	£15.50
81A-16754	Bumper (bonnet side panel), E493A, E494A and 103E.....	£0.95
81A-16760	Bumper (bonnet dowel locating) fits E493A.....	£3.90
	Grommet-gearbox cover.....	£4.60
	Set of three grommets-gearbox cover.....	£12.20
CE-171515A	Grommet (windscreen wiper).....	£3.50
E93A-17772 / 3	E93A Prefect / Anglia / 103E Bumper Grommets (pair).....	£19.99
E493A-17772/3-B	E493A Prefect Bumper Grommets (pair).....	£32.25
E93A-35184	Pedal plate rubber bumper (Saloons and Scwt vans 1939 onwards).....	£1.99
E83W-111172	Opening windscreen rubber for E83W.....	£21.30
48-702610A	Door post rubber bumper (one per door post 1937 onwards).....	£2.50
E04A-7040318	Rear no plate rubber bumper (Anglia and Popular 1939 onwards).....	£2.20
100E-7043531	Boot T Handle Escutcheon rubber seal.....	£4.50
62E-731942	E83W Door Rubber seal (enough for both doors).....	£16.95
7W-940502	Opening windscreen rubber for Prefect and Scwt van.....	£18.30
7Y-940502-B	Front screen rubber for 103E/E494A/E04A.....	£19.50
7W-941480 / 1	Weatherstrip door bottom (per ft) all saloons 1937 onwards.....	£2.80
7W-970700	Roof weatherstrip (per foot) All models except Y and C.....	£2.30
103E-7025856	Rear screen rubber for all saloons (not E93A or 7Y deluxe).....	£15.50

Miscellaneous Body Fittings

E93A-5036	Tube (starting handle guide) assembly – 103E Popular.....	£28.99
E493A-5036	Tube (starting handle guide) assembly – E493A Prefect.....	£30.99
E03CF/A-8213	Grille Badge, "Thames" (blue enamel) (E83W).....	£12.70
103E-8213-A	Ford Popular Grille Badge (103E Popular).....	£9.99
E494A-8215	E494A/E494C/103E Grille Badge Mount.....	£14.95
E83W-8215-A	E83W Grille Badge Mount.....	£19.50
E04A-16719-B	E04A/103E Boot Lid Escutcheon (fits over coach key hole).....	£5.99
YE-16750B	Bonnet Clip (Y model).....	£19.95
	Starting handle.....	£45.00
Y-17275	Gasket (Speedo drive cap).....	£1.95
103E-17261 / 2-B	Speedo Cable (not E83W).....	£26.00
	Speedo Cable (E83W).....	£23.95
C46412AR	Dovetail (female).....	£4.35
E93A-7022400-A	Door handles and escutcheons-pair (Anglia/103E/Scwt van-shafts and barrels not included).....	£49.80
	Locking door handle and escutcheon (shaft and barrel not included) Anglia/103E/Scwt van.....	£29.95
E493A-7022400	E493A Locking Door Handle with escutcheon (shaft and barrel not included).....	£31.60
E93A-7043500	Locking Boot Handle, chrome plated, with keys.....	£12.50
C-943658	Grille Trim Retaining Clip (7W, E494A, E494C, 103E).....	£0.60
BE-964280-H	Window Winder Handle.....	£4.99
7Y-949624	Stainless Steel Door Hinge Pin (All saloons 1938 onwards).....	£4.95
Y-949967A	Striker Plate (Rear door 4 door Y model 1932-1934).....	£4.00
C-949967C	Striker Plate (C and CX, 1934-1936).....	£4.00
	Bootlid Script Badge (Popular, Prefect and Anglia).....	£14.95
	E83W wing mirror.....	£19.99

17

Pop Shopper

Advice from DVLA

The DVLA may refuse to register vehicles without a vehicle identification number (VIN) and/or engine number, and may ask the Police to inspect them.

Readers are advised to think carefully before purchasing such vehicles.

Post-war Upright

1953 Ford Prefect E493A. Belcher Engineering rebuilt 1172cc Engine, including cam followers and conversion to shell bearings (so no white metal problems anymore). Radiator recored. New fuel pump and carburettor. New wiring harness with 12 volt conversion. Panhard rod and four brand new tyres fitted in March this year. Original interior with no damage. All chrome ok and bodywork painted by T.C. Oliver of Bridgend in 1984. Fitted indicators. Owned since 1980. Third owner and I'll be sad to see her go but things change and we have more important things to do. £3,500 ono. Tel: David on 01656 744291 after 7pm or email david.langrish14@gmail.com.

100E & 107E

1956 100E Prefect. Log book present but I've lost the registration. Engine out and possibly U/S. Gearbox out and overhauled. Body suffering from years under a tarp. Includes stripped parts of another 100E (also 1956) and all parts in various condition but minus body shell – including glass and body panels, running gear etc, etc. Project started 12 years ago but abandoned due to illness (ex-FSOC member). She needs a good home. I can e-mail an extensive photo selection of car and parts to anyone interested. All offers considered. Stansted Airport area. Tel: Neil Thurgood on 01279 503261 or email multiverse42@hotmail.com. (Non-member)

Commercials

E83W project. Rough and needs full restoration. Comes with spare rolling chassis and V5 in my name, plus an extra driver's seat. Two very good rear doors, also wings, grille, bonnet and ten new repair panels (small sections). Condition of engine unknown. Worst area of repair will be the door hinge sections (I have repair sections). Please call me if really interested – first come, first served. £2000. Bristol. Tel: Michael on 01179 603773 or 07771 511233 or email mikewitts@aol.com. (Non-member)

1960 Ford Thames 300E. 54,000 miles. Fully restored. New MoT. Recently serviced. £7495.00 ono. Tel: Nick Rudd on 01702 257185 or email wallakers@aol.com. (Non-member)

Wanted

Various 100E trim parts. Two good hub caps wanted for 1958 100E Prefect and three chrome joiners for front and rear screen surrounds please. South West. Tel: 07875 407353.

Prefect or 7W Upright. E93A, E493A or 7W (4 door). Prefer unfinished project but anything considered – must have V5C. Burnley. Tel: Brian on 01282 437234 or email brian.nutter@virginmedia.com.

Special – particularly a competition car. I'm looking for an early Special, either a full runner or restoration project. I will consider anything offered and am particularly interested in any early race cars used for circuit racing, sprinting or hill climb events. Please contact me if you have anything of interest. Berkshire. Tel: Mark Ranger on 07834 032188 or email m.ranger63@gmail.com.

Temperature gauge and sensor for 1953 Prefect E493A. Lincolnshire. Tel: Clive Brown on 01472 851661 or email brown.clive@tiscali.co.uk.

Pinion bearing spacer. Part number 4611 for the rear axle of E83W. Also 16" wheels for E83W pick-up. North Cornwall. Tel: Joe Caudle on 01566 774963 or email joe.caudle@btinternet.com.

Crown Wheel and Pinion for E93A/Ford 10 Diff. 4.1 to 1, or 3.9 to 1, but would go taller, 3.7? Good price paid. North London. Tel: Adrian on 01923 721138 or 07901 820603 or email adrian.leveridge@smithsdetection.com.

Spares for sale

Breaking Upright Sidevalves. E493A Prefect and 103E Popular – most parts available including opening 'screen, engines (can be heard running), gearboxes, axles, very good bakelite dashboard, etc. Merseyside. Tel: David Rothwell on 01704 211908 or 07860 266949.

Four-speed gearbox. 4-speed Morris/MG gearbox & Ford bell-housing to fit E93A. Surplus to requirements. Leicestershire. Tel: Toby Hewison on 07866 891981 or email hewison@freenetname.co.uk.

Various Sidevalve parts for sale. 103E various brake parts inc drums, shoes, backplates, stub axles, king pins. 100E drums and shoes, steering draglink &

idler, bonnet, 100E/300E radiators, Escort rear quarter bumpers, starters, dynamos, steering box, heater matrix, crankshaft, cylinder head, vacuum tank, anti-roll bar, new pistons (part set). Front & rear windscreen, new 100E oil pump gears. Wheels, air filters, headlamp bezels, 300E reflectors, 300E exhaust system, 100E handbrake cable, various other bits & pieces. Tel: Andy Rayfield on 0208 656 7350 or email Andrew.Rayfield@BTinternet.com.

Various Sidevalve parts for sale. 1. NOS Smith 6V heater with original hoses (unused and uncut) and most of the original box Model R150, needs to be used with a water pump. Car hose connectors also available. £45.00. 2. Radiator for a Ford special – Serck model D4929. Core is approx 490 x 430 mm, 25 mm flange top and bottom with holes at 240 mm (top) and 430 mm (bottom) centres. Drain tap near side, top hose 42 mm, bottom hose 32 mm. £40.00 – collect only. Gloucester. Email p.a.birch@btinternet.com.

Sidevalve engine and gearbox. Possibly Model C – has crude hose connections on engine block and handbrake is bolted to gearbox. Offers please. Engine in Birmingham. Tel: J. Clarke on 01782 796595 or 01782 796882 or email jclarke@hotmail.com.

Ford Popular 103E (etc.) parts. Full set of seats in red for 1955 model £150. Popular hub caps £3 each. Early hub caps £5 each. Fog light complete £30. Pair of headlights (with stems, glasses and rims but incomplete) £60. Cambs. Tel: Michael on 01945 464892.

Miscellaneous

Various books for sale. Special Builder's Manual (July '59), 44 pages, Ford Special Builder's Guide & price List (c. 1959) and Sports Car Tuning Instructions (1958?), 59 pages – all £10 each plus postage. Building and Racing My 750 (1961), 112 pages, £20. Watford. Tel: Tony on 01923 231699.

All advertisements here are accepted in good faith. Buyers are reminded to check any expensive purchases before parting with their money.

Remember that these adverts also appear on the club website: www.fsoc.co.uk



Sidevalve News

Sidevalve News is published every two months on the fifteenth of the month, commencing February.

Please email your adverts to pop.shopper@fsoc.co.uk or use the advert page on the web at www.fsoc.co.uk or post this form to:

Mark Bradbury
10 Pettyfields Close
Knowle
Solihull
West Midlands
B93 9EG

Classified advertisements appear at the editor's discretion, and are subject to submission to the editor by the tenth of the month preceding publication.

This is a free service for both members and non-members, although an individual may not normally have more than two advertisements in any one issue.

Please complete this form in **BLOCK CAPITALS** and include your area and phone number.

The FSOC's status as a mutual trading company precludes the acceptance of paid advertising from third parties who are not fully paid-up members of the FSOC.

Trade advertisements from members whose income derives in whole or part from the sale of spares or vehicles must be pre-paid, at £10 for each 28 word insertion. Please make cheques payable to *Ford Sidevalve Owners' Club Limited*.

Advertisements must be with the Editor by first post on the 10th of the month preceding publication.

Year (e.g. 1961)	Model (e.g. 100E)	Model Type (e.g. Prefect)	
Region		Telephone (include STD Code)	E-mail address (if applicable)

Please indicate heading: ☐ For Sale ☐ Wanted

☐ Pre-war ☐ Post-war upright ☐ 100E/107E

☐ Special ☐ Spares ☐ Miscellaneous

☐ Other (please state)

Name _____

Address _____

FSOC Membership No _____

Email address _____

You may photocopy this page if you prefer.



Please fill in the whole form including official use box using a ball point pen and send it to:

Membership Secretary
The Ford Sidevalve Owners' Club Ltd
PO Box 8095
Bishops Stortford
Hertfordshire
CM23 4XZ

Name(s) of account holder(s)

Bank/building society account number

--	--	--	--	--	--	--	--

Branch sort code

--	--	--	--	--	--

Name and full postal address of your bank or building society

To the Manager	Bank/building society
Address	
Postcode	

Reference

F	S	O	C	S	U	B	S								
---	---	---	---	---	---	---	---	--	--	--	--	--	--	--	--

Banks and building societies may not accept Direct Debit instructions from some types of account.

This guarantee should be detached and retained by the Payer.

The Direct Debit Guarantee



- This Guarantee is offered by all banks and building societies that accept instructions to pay Direct Debits.
- If there are any changes to the amount, date or frequency of your Direct Debit FSOC Ltd will notify you 10 working days in advance of your account being debited or as otherwise agreed. If you request FSOC Ltd to collect a payment, confirmation of the amount and date will be given to you at the time of the request.
- If an error is made in the payment of your Direct Debit, by FSOC Ltd or your bank or building society, you are entitled to a full and immediate refund of the amount paid from your bank or building society.
- If you receive a refund you are not entitled to, you must pay it back when FSOC Ltd asks you to.
- You can cancel a Direct Debit at any time by simply contacting your bank or building society. Written confirmation may be required. Please also notify us.

Instruction to your bank or building society to pay by Direct Debit.

Service user number

6	3	0	6	5	6
---	---	---	---	---	---

FOR FSOC LTD OFFICIAL USE ONLY

This is not part of the instruction to your bank or building society

THE FSOC UNDERTAKE TO USE THIS DIRECT DEBIT MANDATE FOR ANNUAL MEMBERSHIP SUBSCRIPTIONS ONLY.

MEMBERS - PLEASE COMPLETE YOUR MEMBERSHIP NUMBER BELOW:

FSOC MEMBERSHIP NO: _____

Instruction to your bank or building society
Please pay FSOC Ltd Direct Debits from the account detailed in this instruction subject to the safeguards assured by the Direct Debit Guarantee. I understand that this instruction may remain with FSOC Ltd and if so, details will be passed electronically to my bank/building society.

Signature(s)

Date

E83W Register contd




Photo 5

during snowy weather usually in a day. One E83W was actually found on a railway line with the snow so deep the railways could not run, while another persevered in the inclement weather for some 13 days in order to travel from Morecambe to Plymouth. The motto at the time was 'Take an hour longer ... but get there and don't let the public down.'

The Ford Model Ys were identified as 'Double Minstrel Acts' with just two personnel, the driver and passenger. Due to weight, there was no baby piano in the back for the Model Y, just an accordion. The E83W van FYR 837 is seen with its four crew ... From the looks of things in photos 5 and 6, they probably have bartered the piano for more drinks than desired.

Canada News

Les Foster: My Anthony Hoist E83W pickup is under complete restoration in all respects. Currently, friends are helping me rebuild the Anthony Hoist box. We are replacing the complete floor with the exception of the front main cross-member, otherwise everything else will be new metal down there. The bottom two inches of the sides, which are bent 90 degrees to form a flange that attaches to the floor plate, will also be replaced. Patches on the base of



Photo 6

the uprights at the four corners and a new rear cross-member will also be necessary.

To this end, my friend and fellow British vehicle enthusiast, Gerry Parkinson, has drawn up a plan of how efficiently to extract the complete floor plate, metal strips for folding into all the floor channel members, and the box front wall and its top cross-member from two four by eight foot sheets of 18 gauge sheet metal. Enough will be left over for smaller patching needs and the two long patches needed to replace the bottom two inches of the box sides (these are identified on the plan as the 'flanges'). We'll do these in two sections per side as our metal brake is limited to a maximum length of four feet. Two feet of two by one-quarter inch flat bar stock will also be required to replace the plates that locate the rods that mount the box to the truck chassis. The rods can be made of threaded rod or plain rod hand-threaded at their ends. I thought that this information might



Photo 7

make the task of re-building an Anthony Hoist box easier for our members.

Yvon: Les has sent me the full details re the efficient manner to obtain metalwork from the sheets of metal, detailed with all the figure work and dimensions concerned worked out. His info sheets are available to those interested and the three detailed pages will be placed in the archives for future use. Thanks again, Les – this will save a lot of work for those undertaking metalwork on the Anthony Hoists version of the E83W.

Photo 7 shows Gerry triumphantly wielding his plasma cutter after removing the rotten floor from my Thames box. Also replaced was the box's rear main cross-member with heavy square tubing, which had one side cut off to accommodate the ends of the channel members as was done originally.

Panhard Rod kits for Uprights

John Porter

The FSOC is looking into the production of Panhard Rods for the 1937 to 1959 Uprights. The plan is to produce kits of the rear Panhard Rod first with the front one to follow. For this plan to go ahead we do need a response from owners of Upright models: namely, are you interested in buying a Panhard Rod kit for your car? For those of you that do not know what this device does:

A Panhard rod is a component of a car suspension system that provides lateral location of the axle (front or rear), originally invented by the Panhard automobile company of France in the early twentieth century. While the purpose of the suspension of an Upright Sidevalve is to allow the wheels to move vertically with respect to the body, it is undesirable to allow them to move side to side (laterally) which is why our cars

wander and sway on uneven roads. The Panhard rod is designed to prevent lateral movement and is a simple device. It consists of a rigid bar running sideways in the same plane as the axle, connecting one end of the axle to the car body or chassis (in our case, the spring U bolts). The rod is attached on either end with rubber lined bushes that permit it to swivel upwards and downwards only, so that the axle is allowed to move in the

vertical plane only. These were very popular (sorry!) in the 50s and were often sold by the Ford garages to uprate your Pop.

These rods are also essential for Ford Specials to prevent the handling from resembling a puppy on ice! So, if you are interested, please register your interest with John Porter for rear, and later front, Panhard rod kits.



Tony Lloyd

A strange thing

It is funny how one thing leads to another. Take the other day for instance. I was writing a letter to John Duckenfield because I could not attend the Regional Contacts meeting. I was writing about how the time when our cars are remembered as everyday transport is passing into history. We are all getting older and we need to attract a younger element into the Club. It got me thinking and I was trying to remember when was the last time that I personally saw a 100E as everyday transport. For me it was well into the nineties. I remember that there were two ladies who lived in Hornchurch, Essex who had a Green Popular 9382 EV. This car they had loved and owned for many years and it was their everyday transport. One day they used it for a journey to Dagenham and while they were there it was stolen. They were mortified. At the time I was the local organiser for the Essex group (or Regional Contact if you want to be posh) and of course they contacted me to spread the word about the theft. Their car was never found, as I remember, but they went on to buy another 100E which they used for some years as their everyday transport. My memory is not all that clear on this but it must have been close to or soon after the millennium before they changed to a more modern car.

Have you any memories or knowledge of 100Es as everyday transport? Maybe there are some that are still used every day. Let me know if you do know of any.

Rain, rain, rain

This year it seems to have rained forever. Back in April the doommongers were forecasting a major drought. Reservoirs were at their lowest ebb for years. The water companies here in the south east imposed hosepipe bans and had their stand pipes and water tankers at the ready. What happened? Did somebody revive a long lost rain dance? I do not know, but I do know that a lot of summer shows and fetes were cancelled across the country due to the rain. It is therefore with some current interest that our old friend Colm O'Neill has sent a picture of a Prefect that appeared in the *Irish Times*:



Photo: Jimmy McCormack © The Irish Times

The above picture was taken in June 1963 following flash flooding in the suburbs of south Dublin. The woman motorist is being helped by two uniformed busmen and another woman and the atmosphere seems good natured despite what has happened to her Prefect.

To judge by the white dashboard knobs, this car was a late model 100E Deluxe rather than a pre-dogleg 107E. This picture was published again as part of a weekly series called *The Times We Lived In*.

Witty captions, anyone?

Colm O'Neill

MOT news

As you can see elsewhere in this magazine (see Letters & Emails) the DVLA has finally got their act together and sent a letter clarifying the situation regarding the new MOT regulations for pre 1960 vehicles.

You can check that the DVLA has the year manufacture of your car on their records. If you go to www.taxdisc.direct.gov.uk and enter your registration number, the vehicle information that is then displayed should

include the year of manufacture. If they do not have the year of manufacture and you want it recorded then you will need to supply the relevant supporting information as detailed in their letter.

Where are they now?

This is where we try to find out what has happened to 100Es that have not been heard of for some time. Do they still exist? Have they been scrapped? Are they now hot rods?

The first car this issue is a late Popular. It was last heard of in February 1983 which is almost 30 years ago when Mel Smith was the 100E registrar. At the time the colour was lime green and the registration was 210FHO. The car lived in Worktop and the owner was the sixth custodian.

Another late Popular is grey 660DXD. This car was last heard of in 1984 and lived in Twickenham.

If you know the whereabouts or any information on these two Populares, I would be pleased to hear from you.



Anglia, Prefect & Pop Register

Andy Main

Registrar's Comments

This past year has been described in many ways as challenging – the economy, weather related problems with the farmer's crops, cancelled events and the fall in visitor numbers at many attractions. Therefore it was perhaps helpful that we celebrated the Queen's Diamond Jubilee (even if the weather was not that great) and the Olympics brought some 'gold' cheer.

In October it was announced that the Ford Transit factory at Swaything is to close next year – the last Ford vehicle assembly plant in the UK. For just over a century, Ford has assembled/manufactured vehicles in Britain, at its peak rolling more than 3,000 cars a day off its production lines.

Amongst this gloom it is great that Sidevalve owners are enjoying their hobby. For some of us in previous austere times, when our parents/families purchased their first Sidevalve it then cost around a year's wages. For 3½ times more, a three bedroom house could have been purchased.

It was a privilege to be invited recently to the yearly Regional Groups Contact meeting and listen to their enthusiasm. They give up their spare time to organise and run events, host regular meetings and assist in vehicle inspections. Whilst local group meetings will differ they have one important principal, being run by enthusiastic regional contacts. The Kent group which I attend is very friendly, helpful and assists each other with problems.

New members

We welcome three new register members and one change of ownership. New: Kevin Appleby from Warrington with a 1949 E493A Prefect; Colin Goodwin from Lancashire with a 1949 E494A Anglia; and Trevor Stevenson from Hertfordshire with a 1955 103E Popular. Changing owners is Matthew Jagger from Kent with his 1953 E493A Prefect.

Pump globes

Fuel pumps used to be tall and slim with either a glass or plastic globe on the top, usually with the fuel company name and marketing name.

I photographed the Esso Popular pump globe (photo 1) made from plastic from the mid 1950s at the East Anglia Transport Museum at Carlton Colville, near Lowestoft, Suffolk earlier this year. Was it 2*? Can anyone supply further details?

This period photograph (photo 2) of the Haynes Brothers, Ashford Road, Maidstone, Kent site features Cleveland globes. The 1953 E494A Anglia registration NKP404 parked to the left may well have been supplied by Haynes Brothers. Haynes was originally founded in 1790 as an ironmongery business and is now run by

Andrew Haynes, who is the sixth generation to run this substantial family business. Haynes in Maidstone is Ford's largest dealership in Kent and celebrated their centenary in style in 2011. The photograph is reproduced with the kind permission of Haynes Brothers Ltd.

Emergency breakdown kit

Every car/van should carry an emergency breakdown kit from the Club which comprises points, plugs, rota, condenser, fan belt and distributor cap (1935 onwards), which come packed in a plastic container and costs £60, cheaper than buying the items separately. Also worth having is a spare set of E93A ignition leads at £14.95. **Don't forget that these prices and other spares/regalia item prices are what you pay: there are no hidden extras like postage and packing plus VAT.**

Christmas Quiz

For those cold turkey days after Christmas when you're fed up with the repeats, here is a quiz on the Club. No prizes but answers in February 2013 edition

1. Who founded the 100E Owners Club?
2. To which Kentish town did the founder move to in the 1970s?
3. What model 100E did he own and in what year was it built?



Photo 1 – Esso Popular pump globe

4. How many chairmen have the 100E & FSOC had, and can you name them?
5. In the June 2012 *Sidevalve News*, how many UK regional groups are there? Can you name them without looking at the inside cover?
6. The first National Ford Sidevalve Day was held on Saturday 21st August 1971: where was it held at?
7. What was the cost of membership in 1975?
8. At the 1975 Sidevalve Day John Farrer (now the last founder member of the 100E Owners Club) was a winner in the event called Family Affair. What was his award position?
9. In which year was membership of the 100E Owners Club extended to all 8 & 10hp Ford Sidevalve-powered vehicles including the 107E?



Photo 2 – Haynes, Maidstone

10. In which year did the 100E Owners Club become the FSOC?

Overseas members' Prefects

For many years in the December edition I featured the vehicles of overseas members that had joined during the year. In more recent years this has not always been possible. However I was most pleased that two overseas members joined in late 2011, but missed being featured.

Nils Carlbaum from Allerum, Sweden purchased his E93A Prefect registration AC 4928 (photo 3) on 1st August 2005. Nils acquired it from a friend at university who got it from his grandfather who was the original owner. It was photographed on collection to await restoration. Sadly the interior has been destroyed due to the roof leaking.

Jan Bouma (photo 4) was born in Holland but since 1973 has been living in Germany and is now living in Fassberg. Between 1945–1956 Fassberg was an airbase and from which the RAF was involved in the 1948 Berlin airlift. Jan was in the Dutch military and stationed in Germany as part of NATO. Following the withdrawal of the military in 1993 and with much cheaper living in Germany, Jan's family stayed.

Jan's first car in 1960 was a 1949 Ford Taunus. He then purchased a 1952 model followed by a 1958 Consul, 1964 Zodiac, and during the 1970s/80s several Taunus Granadas. Jan's first love in the world of cars was a Ford and that was the reason the Prefect was bought in March 2004. First registered on 1st August 1953 in England, Jan bought it from a friend in the Netherlands, then with a British age related registration PSJ 922. The original is unknown and it is now registered CE FO50H.

The Prefect was never available new in Germany so they either survive here after being sold by members of the British Forces, or as more recent imports. However the model is rare and therefore gains much interest when displayed.

Since purchased, Jan has de-rusted the chassis and inside of the wings, treated them with a rust resisting coating, and welded the door pillars. Flashing indicators have been fitted which is a German requirement. Jan is now considering a full re-spray.

Register 25 Years Ago – Sidevalve News, December 1987

It was my second year at the helm (steering wheel) of the Register – Your Register.

It had been the worst winter for years, a tropical Easter, wet summer (nothing changes) and hurricane winds followed by flooding. As a daily Sidevalve driver I mentioned how today's motorists drive too close to one's rear bumper. Green shield stamps returned and according to an article in *Commercial Motor* one used to get



Photo 3 – Nils Carlbaum's Prefect

thousands of them for every tanner spent. It took years to fill those saver books to get a toaster, and even longer to get patio furniture. Those with the longest willpower eventually got a Ford Popular after 30 years saving stamps.

Members Profile was of the Scott family from Auckland, New Zealand owning a 1948 E04A Anglia named Mid Night, two 1951 E493A Prefects and a 1952 E494C/B Anglia named Atom Ant.

Mid Night was owned by a disabled driver in the late 1960s, so when they purchased it vacuum hoses were still fitted under the floor that that were used to control the brakes. The hoses went up the steering column and were operated by hand controls just below the steering

wheel. These had since been removed with just the hoses under the floor intact.

Atom Ant had been converted to 12 volt and a 100E engine fitted. '100E into E93A Goes' was an article on how it was done with three sketches on the 100E/E93A modified sump.

Greetings

I would like to thank area contacts Dave Pickett, Yvon P, Martin Hatfield, Nigel Hilling, Robin Thake and Stephen Wood for inspecting vehicles for me this year as part of the process to obtain original/age related registrations.

May I also take this opportunity of wishing you and your families a happy Christmas and New Year and good Sidevalve motoring in 2013.



Photo 4 – Jan Bouma and Prefect

Specials Register

Ian Woodrow

By the time you read this I expect you will all be ready for Christmas. I've put my cars in to hibernation for winter, although providing the weather's not too bad I'll take one of them to Romsey's 11th Annual Boxing Day Classic Car & Bike Meet. This get-together always attracts a great selection of vehicles and is a good opportunity to get outside and burn off any excess Christmas calories!

Hibernation only means checking the antifreeze concentration or draining the cooling system, disconnecting and charging the battery and cleaning the terminals and smearing them with petroleum jelly, covering the vehicle with a breathable dust sheet and putting a calcium chloride dehumidifier in the car.

I've received a steady trickle of Specials information during the autumn, but very few Specials registration forms to enable me to try and get the Specials register in order; if you have sold, bought, made changes or not registered, please email or write for a registration form.

Special Sports Open Top

An interesting Special has been spotted by John Porter for sale on the internet: Special Sports Open Top, 933cc Engine, Tax & MOT, £1995. (See photo)



Special Sports Open Top

I've also received some photos from Italy of a beautiful Falcon Competition; I'm still trying to find out more details about this car. (See photo)

Falcon Bermuda Reunited

A few people have expressed an interest in Adrian Leveridge's 4-speed gearbox conversion detailed in the last issue. Adrian has now managed to trace the original builder of his Falcon Bermuda with a Leslie Ballamy chassis.

Adrian writes: I am pleased to announce that the mystery surrounding my Special has been resolved, as I have managed to track down the original builder Mr C. P. Relf of Hawkhurst Kent. (Charles Peter, though goes by the name Peter.) (See photo)



Falcon Competition

I purchased the car in the early nineties, as just a bodywork and a LMB chassis; all other components of the reputedly complete car were missing.

Back in 1961 Peter, who was only 18, bought the Ballamy chassis with a view to making a useable Special: this would be the equivalent of nearly £2000 in today's money, so not an insignificant investment to start with. He had intended using a boxed-in Ford chassis, but on stripping the body off a donor vehicle he considered the chassis to be a lot of work.

The owner of the place where he worked as an auto mechanic was involved in stock car racing and was aware of LMB because of his Independent Front Suspension, and recommended he have a look at the LMB chassis. This Peter liked, so he purchased one.

Over a year later he ordered a bodywork from a component supplier somewhere in North London. Peter recalls that he was a little surprised by the lack of customer attention he was afforded, and likened the service to be as if he were buying a few nuts and bolts, not spending a good three weeks salary on a bodywork.

He never finished the car; although it was complete, he does remember that there was something significantly wrong with the build. I know that the front body support fouled the track rods during cornering, and that the mounting of the rear axle relied on the boot floor for support. I have modified these problems, as neither of these would have made the car safe to drive. The definitive cause Peter could not recall, but one of these is where my money is.



Falcon Bermuda

Courting and moving into a flat in Stevenage with his girlfriend (now wife) that was nearer his then current work meant that he could not dedicate time to finish off the project, so it stalled. He lost his free storage in 1967 when his parents moved house, and after spending the equivalent of thousands of pounds Peter gave the complete car, with the sales receipts for the chassis and body shell, to his friend who was involved in stock cars. It was still unfinished but the friend said he would complete it. He clearly never did, as the problems with the build were still evident when I purchased the remains.

Neither Peter or I know who stripped the car of all of its components – Engine (rebuilt with balanced crank, flywheel, aquaplane head and twin carbs), close ratio gearbox, with Wooler remote, rear axle with high ratio diff, 15 inch wheels, bucket seats and all the dials and gauges. However replacements have been found – although now it is supercharged, and fitted with a Wolseley 4-speed gearbox modified to fit.

Peter recalls that it was at the time just a project, and that even if he had finished the

E93A MODELS

Rear Axle Ratio	Tyre Size	Gearbox	1st Speed	2nd Speed	Top Speed
4.4:1	4.50 x 17	Std E93A	33	58	103
4.4:1	135 x 15	Std E93A	30	52	93
4.7:1	4.50 x 17	Std E93A	31	54	96
4.7:1	135 x 15	Std E93A	28	49	87
5.5:1	4.50 x 17	Std E93A	27	47	82
5.5:1	135 x 15	Std E93A	24	42	74

car, it would have been sold in the subsequent years.

He drove the Bermuda for the first time since starting the build in 1961. I hope it brought back some fond memories.

Peter is still actively involved with motor vehicles and has just purchased a dismantled Austin 7 Ruby to restore. Perhaps it will be a Ford Special next time?

Back axle gear ratios

Adrian's Falcon Bermuda is fitted with a 4.4:1 rear axle and 15" Ballamy wheels, with a supercharged 100E engine. Sometimes a 4.4:1 rear axle ratio is too high, especially when 17" wheels are used. The standard E93A rear axle has a final drive of 5.5:1. Although this ratio is fine for the Ford saloon, a light Special would be undergeared if this ratio is used. Alternative crown wheel and pinion sets are available for the rear axle with 4.7:1 or 4.4:1 ratios.

The chart 'E93A Models' gives an indication of the car speeds if the engine was to run at 6000rpm.

If the Special is overgeared, acceleration will suffer and good use will not be made of the gearbox.

As a rough guide, a normal fibreglass bodied 10hp Special with 17" wheels should have a 4.7:1 rear axle ratio. A Special with 10hp engine, mildly tuned, is capable of pulling a 4.4:1, providing 135 x 15 wheels are fitted. The 5.5:1 axle ratio is recommended with 17" wheels, or 4.7:1 with 15" wheels when using the 8hp engine.

The speedometer for Specials

Many Specials are fitted with a higher ratio back axle (4.7:1 or 4.4:1) and smaller wheels which affects the speedometer accuracy.

NUMBER OF SPEEDO CABLE TURNS PER MILE:

	5.5 axle ratio	4.7 axle ratio	4.4 axle ratio
5.00 x 15 tyre	1016 TPM	868 TPM	812 TPM
4.50 x 17 tyre	984 TPM	841 TPM	787 TPM

The following calculations can be used to determine the error. (Of course, if the original 5.5:1 rear axle and 17" wheels are used with the original speedometer, then no error occurs.)

Some speedometers have the Turns Per Mile (TPM) printed on the dial. The number of turns the cable makes in a mile can be checked by using the following formula:

$$\frac{\text{No. of tyre revs, per mile} \times \text{axle ratio}}{\text{Speedometer drive ratio}}$$

The tyre revolutions per mile may be calculated by dividing the circumference of the tyre into the number of feet in a mile (5280ft).

The gear ratio of the speedometer drive on the E93A engine is 26:6 = 4.33:1, whilst that on the 100E is 12:3 = 4.0:1.

100E calculations

Normally a 100E is fitted with 5.20 x 13 tyres and 4.429 axle ratio. Tyres 11.14", tyre revs per mile = 905. (Details from the workshop manual.)

Number of turns the speedo cable makes per mile = $905 \times 4.429 / 4 = 1002$.

The number on the 100E speedometer is actually 1000.

E93A calculations

The circumference of a 135 x 15 tyre is the diameter, 23 3/4", multiplied by π which equals 6 ft 1 in. This figure divided into 5,280 ft gives an answer of 867 tyre revolutions per mile.

The circumference of a 4.50 x 17 tyre is the diameter, 26 in., multiplied by π which equals 6 ft 9 3/4 in. This figure divided into 5,280 ft gives an answer of 775 tyre revolutions per mile.

The chart below shows the number of speedo cable turns per mile.

So if your Special is fitted with a 4.4:1 rear axle with 17" wheels and a standard

speedometer, when the speedometer reads 40mph you may be travelling at 50mph.

Improved mileage recording and speed indication accuracy could be achieved by:

- finding and fitting a speedometer with the correct TPM
- connecting the speedometer flexible drive cable via a gearbox
- rescaling the dial of the speedometer. (The reading from the odometer will require multiplying by a correction factor.)

Electronic programmable speedometers are available that work from a magnetic pulse picked up from the prop shaft and GPS speedometers, but in my opinion electronic devices are out of character for a Ford Pop-based Special.

Letter from America

The photo shows Shaun Henderson in his 1923 Amilcar-Ford Voiturette Special at a track called Lime Rock Park in Salisbury, Connecticut.



Amilcar

Shaun writes: This track is approximately the same size and topography as Brands Hatch Club circuit. My car laps in 125 seconds for the 1.5 miles, average speed a little over 60 mph. Top speed is about 80mph. We compete in the Pre-War class with about thirty other competitors.

My car has a 1937 Ford 8hp 923cc engine, supercharged, producing about 36bhp.

We have spent the past two years doing a chassis, suspension and brake rebuild to a very high quality race standard. The engine will be rebuilt internally this winter with a Phoenix solid billet crankshaft and con rods, new oil pump, A&E pistons, balanced and blueprinted. We are aiming for 75bhp. New top speed should be 110+ mph. Car weighs 970 lbs.

2013

To anyone who's got a Special stored away, I hope you will make a New Year's resolution to get it out and get it back on the road. Merry Christmas and a Happy New Year.

Letters & Emails

**SVN Editor,
PO Box 1172,
Abingdon S.O.,
OX14 5WA**
**E-mail:
editor@fsoc.co.uk**

Moving on at the end of an era

Dear Sidevalve,

Just a note to say that after 30 years in the FSOC I have decided not to renew my membership this year. Over the years we have owned such diverse cars from E493A Prefect, 103 Pop and 100E Escort to a couple of dozen fibreglass specials including Falcons, Ashley, Tornado, Convair, Rochdales, Speedex and others I have long forgotten. I helped organise Historic Specials Shows at Burford, and the Club stands at the NEC shows for years, and to run the Coventry group for a few years. Latterly I have run the Specials Register and since 2001 the 1950specials.com website.

However over the last few years my interest had diminished and the enthusiasm had gone, and I was hankering for a tin top again. I was thinking of just selling one Special, but thought that I wouldn't be able to get very much for the £3-4,000 I would get. I suddenly decided to sell both. Then, if I had no cars I wouldn't need the spares, so the idea to sell up completely and have a complete change in direction was born.

A lot of my friends now own the cars we all dreamed of when we were younger – 1950s Americans, so I thought, with all the money I could potentially get from the sale of the Sidevalve stuff I could buy a real nice one. It didn't take long to sell the Specials and the spares and in the meantime I looked around for a suitable car.

Four criteria needed to be satisfied. 1: it had to fit in the garage – I had about a 17ft limit. 2: it had to have a reasonable spares source. 3: it had to be not too thirsty. And 4: it wasn't to be one of the more common types and had to have bags of style and the early 50s look that I love.

After lots of reading and talking to people it soon transpired that I needed a Chevrolet, due to the sheer amount that were made. I also decided that 1953 was the most stylish year of the lot. Up to the mid 1950s Chevrolet sold more cars than Ford and were the biggest selling vehicle manufacturer in the world at that time. This meant that spares are plentiful. Friends told me that theirs get mpg in the low to mid 20s, so that nailed it.

Now, which model? In 1953 Chevrolet made 17 variants of the one car and I settled on the most stylish, the Bel Air Sport Coupé. I found a car in Louisiana. I spoke to the owner, had it inspected

and did the deal. I got an agent to pick the car up and deliver it to the port of Brunswick; he also sorted out the shipping and duties etc and delivered it to my door for £1725. We absolutely love the car, it has renewed our enthusiasm and I want to be driving it all the time. I have a nice stereo in the car playing the 50s sounds that we love, but the sound of those twin straight-through pipes is so amazing that we rarely play it. Another friend who lives a few miles from me has since bought one, so our group is now as big as the local Sidevalve group was those 30 years ago and we have as much fun.



We have made many friends through the Sidevalve Club over the years and had many great times that will never be forgotten. Sue and I would like to wish the Club and its members all the best for the future and long may it prosper.

Yours,

Rob Daniels

Dynamo and cut-out

Dear Sidevalve,

My dear friend John Pole recently wrote a superb article on our Upright Fords and referred to the detailed workshop manual. Recently, though, I found that I required further information for my 1955 Ford Popular 103E. My car has the three brush generator and cut-out that is mounted on the bulkhead. A flickering and then non-existent charge rate over a considerable period of time led me to suspect the ammeter. I substituted a spare but to no avail and then wondered about the dynamo and cut-out. A year ago I had purchased at a flea market a 1930s 'Modern Motor Engineer' (by Caxton Press) set of five manuals. There was a section on cut-outs. I then cleaned the contacts, adjusted the gap and all was well and an immediate charge shown, thus leaving me only to adjust the third brush on the generator to suit my driving style.

My car now starts more quickly, even on a 6 volt battery, runs better and has brighter lights. Hopefully, this article may help other Ford owners.

I welcome articles of a practical nature in our great magazine and wonder if someone is knowledgeable about leaking carburettors?

If I can be of help over the charging rate, please do give me a call on 01684 561383.

Yours,

Richard Southall

Abandoned Pop

Dear Sidevalve,

I am not sure if it is of interest but attached is a picture of a Pop in the middle of London, taken in September.

It is behind a wall. I tried to find out who owned it two years ago but nobody knew. I wanted to buy it then but since got one in better condition.

I took lots of pictures including number plate, chassis plate and under the bonnet. The engine is all there though I am not sure of condition. The body is pretty well shot with dents everywhere.

If anyone is interested I will forward more details and pictures.

Yours,

Colin Goodwin



Letters & Emails contd

Mounting a 12V dynamo

Dear Sidevalve,

I do not know how others have mounted a 12V dynamo, but I use an early type 8HP head on a 10HP engine, and this has what I call the 'peg and saddle' mounting for the old 6V 3-brush dynamo.

To fit the larger 12V dynamo during a recent conversion, a friend welded onto the small saddle piece a much larger saddle made from a piece of 4" steel pipe, long enough to cradle the whole length of the dynamo. The strap around the dynamo just needed a new and longer tensioning bolt to hold down the new and larger diameter machine.

The photos below show the new saddle, with and without the dynamo in place. I shall probably eventually cut off the triangular lugs on the dynamo, which are for the standard 3-point mounting, but they do no harm where they are.

If readers are surprised by the good access seen, this is on a Morgan F4, not an actual Ford car.

Yours,

David Harland, Poole



Saying thank you – I do that

Dear Sidevalve,

I should like to thank the Committee and members for my presentation of that very nice steering wheel trophy at the AGM, and to Richard Glen and our lot for the mounted 100E piston. I think Richard has done wonders for our Southern section. Glen, like Robin in N. London, you will always find under the bonnet of any ailing Sidevalve giving it the kiss of life.

Thanking you all,

John (I Don't Do That) Farrer



Hazelcar

Dear Sidevalve,

Earlier this year I visited the Bentley Wildfowl and Motor Museum, not far from Lewes in East Sussex, and was surprised to see this Hazelcar on display (above and below).

The Hazelcar was made locally near Brighton and was powered by a Ford 8hp Sidevalve engine, complete with clutch and gearbox, mounted transversely at the rear of the car. The Hazelcar was designed by Eric Hazeldine in the late 1940s and other versions were made during the 1950s. When the Ford engine was in short supply, an electric-

powered model was produced. Interestingly, a Coventry Climax fire pump engine was tried, though this proved to be unsuccessful. Now, wasn't this the engine later developed to power the Hillman Imp?

For a lot more information on this little Ford Sidevalve powered car, have a look at the website hazelcar.co.uk, where you will find lots of photographs of the cars, newspaper articles and a restoration story.

Yours,

John Skinner



From the DVLA

Dear Sir,

Pre-1960 vehicles

I am writing to notify you of a change in legislation that may impact a number of your members. From 18 November 2012, vehicles manufactured before 1 January 1960 will become exempt from the requirements to have a mandatory MOT test. I can confirm that these vehicles will still be required to be in a roadworthy condition when used on a public road. Keepers of pre-1960 vehicles will still be able to take a voluntary MOT test at all approved testing stations if they wish to do so.

This means that on or after 18 November 2012, keepers of vehicles who need to tax their pre-1960 vehicle(s) will not need to produce a valid MOT pass certificate when applying for a tax disc. Any application to tax via the Post Office or Local Office will require a completed V112 ('Declaration of exemption from MOT testing') where the customer declares that their vehicle is exempt. In addition, the DVLA electronic vehicle licensing system will enable customers with pre-1960 vehicles to tax without a MOT from 18 November 2012.

This exemption will also apply to vehicles where a date of manufacture is not on the Driver and Vehicle Licensing Agency (DVLA) system, but the date of registration is recorded as being on or before 7 January 1960. We also apply this policy to the qualification criteria for the pre-1973 Vehicle Excise Duty exemption.

I can confirm that the Agency will continue to allow pre-1960 vehicles to either transfer or retain their registration mark using the current cherished transfer scheme provided a voluntary MOT has been passed. This is to ensure that vehicles are still in existence and prevent potential fraudulent claims for attractive marks.

Where keepers believe their current vehicle should be exempt due to the law change but their Vehicle Registration Certificate (V5C) does not reflect this, they will need to write to the DVLA to request a change. The address to write to is

DVLA, Swansea, SA99 1BA.

In order to ensure the accuracy and integrity of the vehicle records held at the DVLA, it is important that evidence provided to amend or add information already held on our system is accurate and truly reflects the vehicle for which it is issued. Therefore it has been decided that for these specific cases, requests will only be considered where it has been accompanied with either an extract from the manufacturer/factory record or an extract from the appropriate 'Glass's Check Book'.

The 100E and the Aronde

Dear Sidevalve,

I was very interested in the article in the last *Sidevalve News* comparing these two cars, as I am quite interested in Simca, although I own a 100E Prefect and a 300E van. Then your article reminded me that among my collection of period photographs, I had one with an Anglia and an Aronde together.

The attached image was taken in 1961 in Tullamore, a town in the Irish Midlands. The Anglia standard model has a November 1959 registration, which makes it one of the last of the 100E Anglias. In fact I once had a half share in a pre-dogleg 107E registered CZA 568. I obtained this print from the National Library of Ireland several years ago and got permission to use it in not-for-profit publications such as car club magazines.

The link with Ford and Simca arose in a more direct way when Ford pulled out of France in the early Fifties, much against the advice of Sir Patrick Hennessy, then head of Ford of Britain. Simca acquired Ford's production facilities and the designs and tooling for new models, which appeared as the Simca Ariane, Simca-Vedette Trianon, Versailles, Chambord, etc. Apart from looking a lot like the 204E/206E Zephyr/Zodiac range, the engine compartment structure had very similar McPherson strut mountings and radiator support panel, also to be found in the original Consul/Zephyr/Zodiac E0A range.

Many thanks for an enjoyable article.

Regards,

Colm O'Neill



O'Dea Collection, copyright National Library of Ireland

Both these documents will have a direct link to the chassis number that should already have been accepted and recorded on the vehicle record as part of the initial registration process.

I can confirm that for these specific cases, DVLA will not accept general dating certificates as evidence to amend or update the date of manufacture. Such certificates will however continue to be accepted for other purposes such as V765 claims and requests for

age related numbers for recently restored or recently imported vehicles.

I trust this explains the situation.

Yours sincerely

Claire Rush
Corporate Affairs Directorate

Winter-Starting Old Sidevalves

David Harland

Just to remind readers, I am the member who owned a Ford-powered Morgan 3-wheeler (Model F4) in the early 1960s and who got it back and restored it in this century.

I am commenting on the article in the October 2012 edition of *Sidevalve News* in which an owner comments about the difficulty of winter-starting an Upright Prefect.

I think that we are totally spoiled by modern cars which we expect to start instantly, even when covered in frost or condensation, and they usually do. It was not like this in the past! I remember that in cold weather, despite normally garaging or covering the car, for those of us with pre-war cars, or ones using pre-war technology, the first challenge on a winter morning was to get the car started, and one needed to allow time for this. We did not take it for granted that it would start on demand.

Half a century ago and more, people who needed to use their cars regularly normally

kept them in a garage, not left open to all weathers. This was partly because in earlier times anti-freeze was simply not available to the public, so to prevent frost damage it was normal either to drain the cooling system on a frosty night and refill it (if lucky with warm water!) in the morning, or to have a heater (often paraffin-burning!) under the sump all night.

By the time I owned a car (the Morgan) in 1960, antifreeze was available, based on ethylene glycol, which I believe was used in Merlin aero engine cooling systems in the war. I used glycol coolant antifreeze but did not have any pre-heat advantage so I sometimes adopted what now we would think of as extreme measures. Firstly, in cold weather, the warm engine was wrapped in old blankets on arrival home and the bonnet closed again on it. Then, with only 6 volts available it was a complete gamble whether it would start 'on the button' on a cold morning. As the cranking speed was so sluggish I usually used the starting handle anyway for a cold start, and have continued to do so until recently when I have converted to 12 volts. I can also

vividly remember, after a failed start on frosty mornings, taking out all four spark plugs, probably now wet with excess fuel, drying and warming them around a gas burner in the kitchen, then refitting them as hot as I could handle and starting the engine as quickly as possible afterwards, before they cooled completely. I also have a friend who tells me she often played a hair drier under the bonnet of her 'modern' car around 1960 in order to get it to start on winter mornings.

In the 1960s the Morgan was my everyday transport. Now it is kept only as a hobby so I do not need to cold start it so often, but I know that when I do it may take some time and trouble. I have just (in September 2012) converted to 12 volts and the engine certainly cranks briskly but I do not yet have any experience of really cold-weather starts with 12V available.

Perhaps one of our technical experts would also comment, and give some advice to younger drivers on techniques and possible tricks to help cold starting of our ancient types of engine. The notes above are simply from my own personal experience.

Cotswold Historic Sporting Trial

Martyn Halliday

3rd November 2012

Stroud and District Motor Club held their first Historic Sporting Trial at Horsley in Gloucestershire and welcomed an excellent entry of 18 pre-1974 trials cars. In line with the inaugural trial in May the field was classified into four groups depending on the level of modification of the car. In an attempt to promote pre-1970 specification, the main award would go to the winner of class A: those cars that were running 18 inch rear wheels, transverse leaf spring front suspension, fiddle brakes and 1172cc sidevalve engines. As it happened this was the largest class which was made up mainly of Cannons, plus John Heppenstall in the Cotton Cannon and Ian Veale in the IRH2. In all nine cars had 1172cc engines.

Conditions were near perfect, crisp and clear but suitably damp underfoot. The seven sections had been laid out with both this and the ability of the cars entering in mind. At the end of the first round (of five) there were some very respectable scores from all the classes. Leading overall was Neville Collett (Class A1) in his modified Cannon with a score of 0. Kiel Wright (Class B) driving one of the last Cannons ever to be built had dropped just a

single point while Ian and Nigel Moss (Class B1) were tying on a score of 2. Ian Veale led Class A on 3.

With the passing of cars the sections became more and more slippery and with tyre pressures set at 10psi, power was not necessarily the order of the day. With some of the cars having not seen action for many years a few gremlins understandably started to appear. Martyn Halliday lost a bolt from his front suspension, Kiel and Bianca Wright's engine kept running out of fuel and Richard Neale retired his Dellow after round 1. At lunch (after three rounds) Neville Collett was still ahead with a score of 7 from Ian Veale on 10 and Ian Moss on 13; all the classes well represented on the leader board. Lunch was suitably leisurely with plenty of opportunity

to look over the cars and chew the mechanical cud.

With sections tweaked for the afternoon runs and conditions becoming increasingly difficult, scores started to rise. Hill 3 at the bottom of the site had a brand new start which was tricky enough in round 4 but became very difficult in the final round. Only five competitors managed the first turn, the penalty for failure being 9 or 10 points lost. Despite collecting an unwelcome 10 points here, Neville Collett managed to hang on to win Class A1 with a total of 28 points. Tim Barrington prevailed in Class B while Ian Moss secured Class B1 with only 36 points lost.

First in Class A and therefore overall winner was Ian Veale with a score of 23 points, with his son Tristan as passenger. The winning car was built in 1964 by Ian Headon who drove it with much success during the sixties and early seventies, including three outright wins in the London-Lands End Trial, one of these with Ian Veale's father as passenger. The fact that three generations of the same family can enjoy success in the same car almost 50 years apart sums up the fascination of the HSTA and the desire to bring these old cars out and competing again. Congratulations to Stroud and District Motor Club for providing the latest opportunity in this process.



Photo: www.charliewooding.co.uk

Don't Rely On The MOT ...

David Durrant

The photo of my E83W ONG813 in the October 2012 issue is flattering! In the flesh it is now somewhat scruffy as compared to what it was after I refurbished it in 1991, the story of which subsequently appeared in *Sidevalve News*. Twenty one more years of use, much of which could be classed more accurately as mild abuse, have taken their toll, although in deference to the rust I now prefer not to use it too much in the wet. I must make one minor correction, however, in that I have owned it rather longer than 30 years. I bought it in 1969, so 43 years of use. The present engine is a 'bitsa' and has been in for about 15,000 miles, with no bother apart from the head gasket, which was my own fault. I had fitted an ancient autojumble-sourced part from a manufacturer which I later found out had a poor reputation. The extremely long-lived engine I had in years ago (which was burning a hideous amount of oil by the time it cracked its block and I had to discard it) was one I built up with great care from new and reconditioned parts in 1974 or 1975, and ran in most carefully with graphited oil. There are of course a number of other important factors – amongst which are air and oil filtration, oil change intervals, oil type (about which I could pontificate controversially at some length!) and the additional expedient of an industrial governor, which effectively de-rates the engine and prevents overloading. Yes, it is slower, but not by much, and I'm happy with the trade-off. I still have it fitted.

A few weeks ago I had a call from Chris Winter of Sleaford, whose magnificent coach-built piano transporter van was not running properly, despite various attentions to ignition and carburetion. As it was booked in for a parade in Bourne the following weekend, and time was becoming of the essence, Chris trailered it to my place. Fortunately rectification was not difficult and it was soon running extremely well, and the opportunity

was taken to have a photo shoot with John Wilson's Utilicon, all parked up on my lawn. (See back cover of this issue.) I suspect there are not too many occasions now where three different varieties of E83W can be seen together at short notice. Unfortunately, perhaps, that no pickups were available.

We drove each other's vehicles, a sort of 'compare and contrast' exercise, and herein is my main reason for writing this. I had been aware that my van suffered from some intermittent excess of engine vibration and had been steering badly for three years or so, but I'd checked the tracking, which was okay and nothing obvious was visible. Replacement of the 'A' frame bush gave minimal improvement. MOTs were happily passed without adverse observations. I'd put things down to a combination of poor East Lincolnshire rural roads, worn dampers, worn springs, and some slightly dodgy spring shackles, worn gearbox bearings, and perhaps a rather over used and now somewhat flexible chassis. (Evidence of a little movement has been visible between the front crossmember and the side rails for some while.) I had stiffened up the dampers a bit by adjusting the valves (tedious to get them right, and equal) and anchored a helper spring at the rear, which had only improved matters marginally, at the expense of harsher ride and more rattles. Now, having driven these other two, I was forced to acknowledge how bad the steering had become, and that attention really was necessary.

My van was due for a service, which I duly started a few days after our gathering. One extra item, which I always attend to, is the removal and thorough cleaning of the engine breather/oil filler, which tends to collect condensation and sludge. I don't like the potential for this to get back down into the engine and indeed, if present in real excess, cause some obstruction to crankcase ventilation in particularly cold weather. When replacing the breather, however, I happened

to glance down and notice deterioration of the nearside engine mount. Investigation revealed that this had failed badly, with bolt well seized in the now completely separated centre, with the rubber profoundly degraded. Cause of periodic vibration now evident. Significant deterioration was also present in the offside mount, all very irritating, as they had only been renewed 21 years previously. Fortunately I had a pair of new mounts in stock, but the state of the nearside mount and inaccessibility necessitated the removal of the engine bearer. This was a filthy job, with much accumulated greasy and muddy gunge.

So, with access from underneath being required, it was into the inspection pit. Replacement was straightforward, but in the course of this my attention was drawn to the central spring mount. To my consternation the central bolt was broken, no doubt caused by the 'U' bolts being loose (nuts apparently tight, but threads damaged). The cause of the bad steering was now apparent, with local damage suggesting that this derangement had been going on for some time, with significant lateral movement of the spring, and abnormal lateral interleaf movement. Fortunately the chassis crossmember had little damage, and no broken spring leaves were present. However, some excess strains will have been imparted, and time will tell.

I had replaced the spring in the early 1970s, when the previous one broke, and have subsequently introduced an extra leaf or two to counteract general wear and sagging, so I suppose it's done quite well. And the steering is now much improved, although not, I think, up to the standard of the other E83Ws, so spring shackle bushes, at least, are now on the 'to do' list. Lessons to be learnt – don't ignore unexplained changes, and don't necessarily (and this is now an obsolete observation) rely on the MOT, even if passed without adverse observations by an experienced operator, as mine was.



A taster of Michael Saunders' Siva - full details to follow in February!

